

R. MARSIL JOHNSON  
BLAIR STERLING JOHNSON & MARTINEZ  
A PROFESSIONAL CORPORATION  
238 ARCHBISHOP FLORES ST STE 1008  
HAGĀTNA GU 96910-5205  
TELEPHONE: (671) 477-7857

Attorneys for Appellant Mid Pac Far East

RECEIVED  
OFFICE OF PUBLIC ACCOUNTABILITY  
PROCUREMENT APPEALS  
DATE: 10/2/2015  
TIME: 1:35  AM  PM BY: MSB  
FILE NO OPA-PA: 15-011

## IN THE OFFICE OF PUBLIC ACCOUNTABILITY PROCUREMENT APPEAL

---

In the Appeal of ) Docket No. OPA PA-\_\_\_\_\_  
 )  
MID PAC FAR EAST, )  
 ) NOTICE OF PROCUREMENT APPEAL  
Appellant. )  
 )  
\_\_\_\_\_  
 )

### Appellant Information:

Mid Pac Far East (“MPFE”)

Mailing Address: P.O. Box 20969  
Barrigada, Guam 96921

Business Address: 475 Mendioka St.  
Dededo, Guam 96929

Telephone: (671) 632-5160

### Appeal Information:

- A) Purchasing Agency: General Services Agency (“GSA”)
- B) Identification/Number of Procurement, Solicitation, or Contract: Invitation for Bid No. GSA-093-15.
- C) Decision being appealed was made on September 29, 2015 by Claudia S. Acfalle, GSA’s Chief Procurement Officer.
- D) Appeal is made from a decision on protest of Method, Solicitation or Award.
- E) Names of Competing Bidders, Offerors, or Contractors known to Appellant:
  1. NAPA Auto Parts
  2. Morrico Equipment, LLC
  3. Pacific Petroleum Trading Corporation

**Form and Filing:**

1. On July 31, 2015, GSA issued an Invitation for Bid, GSA-093-15 (“the IFB”), for “Miscellaneous Items & School Bus Parts”.
2. On August 25, 2015, four bidders responded to the IFB and all bids were opened.
3. A Bid Status document, dated September 28, 2015, was provided to MPFE indicating that MPFE’s bid had been rejected due to “[n]o bid security or insufficient bid security.” *See Exhibit “A”*. The Bid Status further remarked: “Standby Letter of credit in the amount of \$42,000.00 (Bid security short by \$2,263.41) Total Amount of Bid Amount: \$295,089.37.” *Id.*
4. The price list per vendor received from GSA indicates that MPFE had mistakenly transposed the decimal in the price per foot in Line Item 79.1, described as “HEATER HOSE (3/4 Inch Inner Diameter) 50 feet Roll”. *See Exhibit “B”*. As a result, the price per foot incorrectly read as \$537.00 per foot instead of \$5.37 per foot. The only other bidder on Line Item 79.1 was Morrico Equipment, LLC (“Morrico”), which indicated a price per foot of \$9.04. Despite the error in the price per foot, the total price per roll was correctly entered at \$268.50 per roll. This price was \$183.50 lower than Morrico, the next lowest bidder, which bid a price per roll of \$452.00.
5. On information and belief, GSA used the mistakenly entered price per foot of \$537.00 and multiplied that figure by 50 to obtain its own price of \$26,850.00 per roll, despite the per roll price of \$268.50 entered by MPFE. GSA then combined its \$26,850.00 per roll price with MPFE’s extended prices for all Line Items in the IFB and came to its own total bid price for MPFE of \$295,089.37. GSA then rejected MPFE’s bid on the basis that the \$42,000.00 standby letter of credit provided by MPFE was insufficient to cover the new total bid price GSA had calculated for MPFE based on the obviously mistakenly entered per foot price of \$537.00.
6. As a result, it appears that all of the line items for which MPFE was the lowest bidder will be awarded to the next lowest bidder instead.

7. The original protest made by MPFE was made on September 28, 2015. *See Exhibit "C".* In the protest, Craig Wade, the President/CFO of MPFE, disagreed with GSA's determination that MPFE's bid bond was insufficient. Mr. Wade noted that MPFE's extended prices totaled \$268,507.87, not \$295,089.37 as erroneously calculated by GSA.

8. GSA responded to MPFE's protest in a letter dated September 29, 2015. *See Exhibit "D".* There, GSA denied the protest, noting that "[i]n reviewing your bid submittal, there was no evidence that a mistake occurred."

9. MPFE is appealing GSA's decision on MPFE's protest on the basis that it is evident on the face of MPFE's bid that the price per foot for Line Item 79.1 entered by MPFE was a mistake and that the intended correct bid is clearly evident on the face of MPFE's bid given the price per roll of \$268.50 which was entered right next to the mistaken figure.

10. 2 GAR Division 4 Section 3109(m)(4)(C) states that:

(C) Mistakes where intended correct bid is evident. If the mistake and the intended correct bid is clearly evident on the face of the bid document, the bid shall be corrected to the intended correct bid and may not be withdrawn. Examples of mistakes that may be clearly evident on the face of the bid document are typographical errors, errors in extending unit prices, transportation errors, and arithmetical errors.

11. MPFE's position is that the \$537.00 per foot price entered in Line Item 79.1 was clearly a typographical error. This is supported by the fact that the \$268.50 price per roll entered in MPFE's bid is the product of \$5.37 multiplied by 50 feet, the fact that the only other bidder for Line Item 79.1 bid \$9.04 per foot, and the fact that the \$42,000.00 standby letter of credit is sufficient if the price per roll entered by MPFE is used to calculate the total bid amount instead of the price per roll calculated by GSA.

12. GSA's decision to exacerbate the typographical error by using it to calculate an absurdly disproportionate price per roll and then reject MPFE's bid in its entirety was improper given the rule on mistakes set forth in 2 GAR Division 4 Section 3109(m)(4)(c).

13. GSA's decision is also improper given 5 G.C.A. §5001(b)(5), which provides that one of the underlying principles and policies of the Guam Procurement Law is "to provide increased economy in territorial activities and to maximize to the fullest extent practicable the purchasing value of public funds of the Territory." GSA's decision to reject MPFE's bid based on a mistake that was obvious on the face of the bid will result in an award for every line item for which MPFE was the lowest bidder to other parties with higher bid prices. This will result in a larger overall cost to the government of Guam.

14. MPFE requests that the Office of the Public Auditor determine that the \$537.00 per foot price was clearly a mistake, determine that the intended correct bid price was clearly evident on the face of the bid document, order that the bid document be corrected to the intended correct bid of \$5.37 per foot, and overturn GSA's rejection of MPFE's bid on the basis of insufficient security.

15. MPFE has attached all supporting documents as exhibits hereto.

**Declaration Regarding Court Action:**

The undersigned party does hereby confirm that to the best of his or her knowledge, no case or action concerning the subject of this Appeal has been commenced in court. All parties are required to and the undersigned party agrees to notify the Office of Public Accountability within 24 hours if court action commences regarding this Appeal or the underlying procurement action.

DATED this 2nd day of October, 2015.

**BLAIR STERLING JOHNSON & MARTINEZ**  
A PROFESSIONAL CORPORATION

BY:   
**R. MARSIL JOHNSON**  
*Attorneys for Appellant Mid Pac Far East*

## VERIFICATION

I, CRAIG WADE, President/CFO for Mid Pac Far East, hereby declare under penalty of perjury under the laws of Guam that I have read the foregoing **NOTICE OF PROCUREMENT APPEAL** and that it is true and correct of my own knowledge, except as to those matters alleged upon information and belief and so to those matters, I believe them to be true.

DATED this 2nd day of October, 2015.



---

CRAIG WADE

U56\49140-NEW  
G:\PLD\RMJ\084-NOTICE OF APPEAL RE MID PAC FAR EAST GSA-093-15.DOCX

# EXHIBIT “A”

GENERAL SERVICE AGENCY  
(Ahensian Setbision Hinirat)  
Government of Guam  
P.O. Box FG, Agana, Guam 96910  
Tel: 477-1710-13 Fax: 472-4217 / 475-1716/27

---

Accountability \* Impartiality \* Competence \* Openness \* Value

---

## BID STATUS

September 28, 2015

**MID PAC FAR EAST**

P.O. Box 20969  
Barrigada, Guam 96921  
Tel: (671) 632-5172 / Fax (671) 632-5167

BID INVITATION NO.: GSA-093-15  
MISCELLANEOUS ITEMS & SCHOOL BUS PARTS

OPENING DATE: August 25, 2015

The following is the result of the above-mentioned bid. Refer to the items checked below.

- [ ] Cancelled (in its entirety), or partially cancelled due to:  
( ) Insufficient funds;  
( ) Change of specifications; or  
( ) Insufficient number of bidders.
- [X] Rejected due to:  
( ) Late submission of bid;  
(X) No bid security or insufficient bid security;  
( ) Not meeting the delivery requirement as stated in the IFB;  
( ) Non-conformance with the specifications;  
( ) High price  
( ) Others

REMARKS: Standby Letter of credit in the amount of \$42,000.00 (Bid security short by \$2,263.41)  
Total Amount of Bid Amount: \$295,089.37

[X] Bid recommended for award: Multiple Awards, Indefinite Quantity Bid (See attached)

REMARKS: Thank you for your participation with this bid. Please send your authorized representative to pickup your original bid status.

Please Print
ACKNOWLEDGEMENT COPY (re-fax to GSA)
Received by: _____
Date: _____
Company/Agency: _____ Pls fax back to: (671) 300-6699

  
CLAUDIA S. ACFALLE  
Chief Procurement Officer

# **EXHIBIT “B”**

Number of Bidders (4)  
 Number of Bids Received (4)  
 Number of IFB Amendments (2)

Department of Administration			GSA-093-15												
Number of Bidders (4)		IFB Number													
Number of Bids Received (4)		Opening Date		Time											
Number of IFB Amendments (2)		8/25/15		9 AM											
<b>Government of Guam ABSTRACT OF IFB</b>															
<b>Description of Supplies or Services</b>															
MISCELLANEOUS ITEMS & SCHOOL BUS PARTS															
OFFEROR(S)	Acceptance Time	Delivery Acceptance	Delivery Specified IN IFB (60 Days)	A	B	C	D	E	F	G	H	Item No.	Qty. Unit		
				A	B	C	D	E	F	G	H	Item No.	Qty. Unit		
NAPA = 2 copies submitted by 11:45 AM	8/25/15			/	/	/	/	/	/	/	/				
Credit 8/24/15 BOG #01-SB-1077, \$7,100.00 - 1 copy literature submitted.				/	/	/	/	/	/	/	/				
Mid-Pacific 2 copies submitted, shall be submitted by 11:45 AM	8/25/15			/	/	/	/	/	/	/	/				
Monaco - 2 copies submitted, GSA #093-15 (allowable)	8:43 AM	8/25/15		/	/	/	/	/	/	/	/				
Cashway Inc Co. 15% off TBA				/	/	/	/	/	/	/	/				
Pacific Petroleum = 2 copies submitted - bid	8/25/15			/	/	/	/	/	/	/	/				
Wood # KHC-13762-10 Dang Yau Ins 15% off TBA															
LEGEND(S)															
(A) Non-Collusion (B) Disclosing Ownership and Commission Affidavit (C) DOL Wage Determination Affidavit (D) Bid-Bond Form (E) Ethical Standards Affidavit (F) No Gratuities or Kickbacks Affidavit (G) Restriction against Sexual Offenders Affidavit (H) Affidavit re Contingent Fees															
TABULATED BY:		(Signature)		DATE:											
<i>John</i>		<i>John</i>		8/25/15											
<i>I hereby certify that all bids received in response to this invitation were opened under my personal supervision and that the same as of all bidders have been entered hereon.</i>															

NAMES OF PERSONS PRESENT AT THE BID OPENING AND WHOM THEY REPRESENT  
(It is not necessary to fill in this portion if date is recorded elsewhere)

Dwaine Blaz 12BPP Auto Parts  
Eric Torres Super 8 Motel  
Eric Montero Moroni 20 872515  
Dominique Del Vecchio Pacific Petroleum Corp S2205  
Vivian Isaacs 270 Morris St 312/257-1111

ADMINISTRATIVE STATEMENT (Where applicable)

ITEM NO.	DESCRIPTION	QTY.	UOM	NAPA	MIDPAC	Moroco	Pac Pet
1.1	FRONT LEAF SPRING ASSY. WITH BUSHING Ref: Front axle No. 1961358 For: 1998 Blue Bird School Bus Vin#: 1BAAGCSA2WF079694	01	EA.	\$ N/B ext: same	\$ 735.- ext: same	\$ 840. <sup>10</sup> ext: same	\$ N/B
2.1	REAR LEAF SPRING ASSY. WITH BUSHING Ref: Rear Axle No. 1565654 For: 1998 Blue Bird School Bus Vin# 1BAAGCSA2WF079694	01	EA.	\$ N/B ext: same	\$ 451.17 ext: same	\$ 710. <sup>47</sup> ext: same	\$ N/B
3.1	DRIVE BELTS Ref: International engine# 1GAT K081124 For: Blue Bird School Buses	05	EA.	\$ N/B ext: 225.45	\$ 45.13 ext: 296.80	\$ 59. <sup>36</sup> ext: 342.55	\$ 15./B
4.1	FUEL PUMP ASSY. Injector Pump For: 2004 Thomas Built School Bus Vin# 1T88N8D24411375700	01	EA.	\$ N/B ext: same	\$ 1,374.- ext: same	\$ 1657. <sup>10</sup> ext: same	\$ N/B
5.1	BRAKE/TAIL LIGHT ASSY 7" For: 1998 Blue Bird School Bus	05	EA.	\$ N/B ext: 113.90	\$ 22.78 ext: 142.55	\$ 28.51 ext: 192.55	\$ N/B
6.1	SOLENOID 12 VOLTS (continuous duty) Ref: PN# 52000103 For: 2004 – 2005 Thomas Built School Buses	05	EA.	\$ N/B ext: 147.55	\$ 29.51 ext: 152.70	\$ 30.54 ext: 152.70	\$ N/B
7.1	CRANK SHAFT MAIN OIL SEAL (rear) Ref: PN# CU4890833 For: Thomas Built School Bus	02	EA.	\$ N/B ext: 77.36	\$ 38.68 ext: 46.66	\$ 44. <sup>66</sup> ext: 53.32	\$ N/B
8.1	TRANSMISSION OUT PUT SHAFT SEAL (at 545 Allison Trans) For: Thomas Built School Bus	02	EA.	\$ N/B ext: 13.22	\$ 545. <sup>66</sup> ext: 63.10	\$ 17.55 ext: 25.10	\$ N/B
9.1	STOP SIGN ASSY. 12 VOLTS MOTOR DRIVE Ref: SN# 371622 For: 1998 GMC/International School Bus	02	EA.	\$ N/B ext: 1158.34	\$ N/B ext: 1158.34	\$ 579.17 ext: 632.54	\$ N/B
10.1	KING PIN ASSY, LEFT Vin#: 1T88N8E2351161133 For: 2005 Thomas Built School Bus	02	EA.	\$ N/B ext: 696.50	\$ 348.28 ext: 704.54	\$ 352. <sup>27</sup> ext: 704.54	\$ N/B
11.1	KING PIN ASSY, RIGHT Vin#: 1T88N8E2351161133 For: 2005 Thomas Built School Bus	02	EA.	\$ N/B ext: 63.12	\$ 371. <sup>50</sup> ext: 672.12	\$ 336. <sup>06</sup> ext: 672.12	\$ N/B
12.1	POWER STEERING HOSE ASSY. (Reservoir to pump side) For: 2005 Thomas Built School Bus	05	EA.	\$ N/B ext: 165.25	\$ 33. <sup>05</sup> ext: 632.60	\$ 126. <sup>52</sup> ext: 632.60	\$ N/B
13.1	POWER STEERING HOSE ASSY. (Return Line) For: 2005 Thomas Built School Bus	05	EA.	\$ N/B ext: 425.65	\$ 84. <sup>93</sup> ext: 328.55	\$ 165. <sup>71</sup> ext: 328.55	\$ N/B
14.1	POWER STEERING HOSE ASSY. (High Pressure Side Pump to Gear Box Side) For: 2005 Thomas Built School Buses	05	EA.	\$ N/B ext: 828.65	\$ 165. <sup>73</sup> ext: 876.80	\$ 175. <sup>36</sup> ext: 876.80	\$ N/B
15.1	ABSORBENT PADS FOR OIL SPILLS T151 SHEETS 53CM X 39 CM (WHITE)	10	BG/CS	\$ 84. <sup>50</sup> ext: 845.-	\$ N/B ext: 1414.-	\$ 141. <sup>40</sup> ext: 20.-	\$ 62.-
16.1	ENGINE COOLANT FULLY FORMULATED	02	DR.	\$ 551. <sup>57</sup> ext: 1,103.15	\$ 142. <sup>61</sup> ext: 1,285.22	\$ 784.- ext: 1,568.-	\$ 504.- ext: 1,008.-

ITEM NO.	DESCRIPTION	QTY.	UOM	NAPA	MDPAC	Monico	Pac-Pac
17.1	FRONT BRAKE SHOES ASSY. VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus	20	EA.	\$ N/B ext 1,544.80	\$ 77.27 ext 2,410.80	\$ 127.37 ext 3747.40	\$ N/B
18.1	REAR BRAKE SHOES ASSY. VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus	20	EA.	\$ N/B ext 2,410.80	\$ 120.54 ext 3747.40	\$ 162.17 ext 533.74	\$ N/B
19.1	OIL COOLER ENGINE (Side of Engine Block) VIN# 1T88N8D2641137565 For: 2004-2005 Thomas Built School Bus	01	EA.	\$ N/B ext same	\$ 350.77 ext same	\$ 369.87 ext same	\$ N/B
20.1	KING PIN ASSY. VIN# 1T88N8D2641137568 For: 2004 Thomas Built School Bus	02	EA.	\$ N/B ext 575.68	\$ 257.37 ext 533.74	\$ 266.87 ext 533.74	\$ N/B
21.1	ENGINE MOUNTS W/BUSHING VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus	04	EA	\$ N/B	\$ N/B	\$ 25.77 ext 100.-	\$ N/B
22.1	TRANSMISSION ASSY. W/TCM For: 2004-2005 School Bus	01	EA.	\$ N/B ext same	\$ 740.82 ext same	\$ 10,223.89 ext same	\$ N/B
23.1	DRIVERS LIGHT MONITOR VIN# 1T88N8D2641137568 For: 2004 Thomas Built School Bus	03	EA.	\$ N/B ext 892.20	\$ 217.40 ext 491.76	\$ 245.73 ext 491.76	\$ N/B
24.1	ALTERNATOR ASSY VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus	02	EA.	\$ N/B ext 650.-	\$ 325.77 ext 650.-	\$ 405.77 ext 810.-	\$ N/B
25.1	BRAKE SLACK ADJUSTER REAR VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus	06	EA.	\$ N/B ext 520.86	\$ 86.80 ext 520.86	\$ 87.77 ext 522.-	\$ N/B
26.1	BRAKE SLACK ADJUSTER FRONT VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus	06	EA.	\$ N/B ext 520.86	\$ 86.81 ext 520.86	\$ 105.91 ext 625.46	\$ N/B
27.1	FRONT WHEEL BEARING INNER WITH RACE VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Buses	06	EA.	\$ N/B ext 162.24	\$ 27.94 ext 162.24	\$ 82.46 ext 497.76	\$ N/B
28.1	FRONT WHEEL BEARING OUTER WITH RACE VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Buses	06	EA.	\$ N/B ext 236.16	\$ 39.36 ext 236.16	\$ 51.84 ext 311.04	\$ N/B
29.1	FRONT WHEEL BEARING SEAL VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Buses	06	EA.	\$ N/B ext 205.38	\$ 39.23 ext 205.38	\$ 36.88 ext 221.28	\$ N/B
30.1	FRONT WHEEL BEARING CAP (HUB) VIN# 1T88N8D2641137568 For: 2004-2005 Thomas Built School Buses	06	EA.	\$ N/B ext 102.-	\$ 17.77 ext 102.-	\$ 33.09 ext 198.54	\$ N/B
31.1	FUEL LINES #1 THRU #6 CYL. W /VIBRATION CLAMPS VIN# 1T88N8D2641137568 For: 2004 Thomas Built School Buses	02	EA	\$ N/B ext 378.-	\$ 109.77 ext 378.-	\$ 249.83 ext 499.66	\$ N/B
32.1	FRONT BRAKE SHOES VIN# 1GDM7T1J2V0514919 For: 1997 GMC School Bus	10	EA.	\$ N/B ext 14,147.70	\$ N/B ext 14,147.70	\$ 727.58 ext 1485.16	\$ N/B
33.1	FRONT BRAKE SHOES VIN# 1GDM7T1J2V0514919 For: 1997 GMC School Bus	04	EA.	\$ N/B ext 924.64	\$ N/B ext 924.64	\$ 231.16 ext 924.64	\$ N/B

ITEM NO.	DESCRIPTION	QTY.	UOM	NAPA	MIDPAC	MONICO	PAC RET
33.1	FRONT BRAKE SHOES VIN#1GDM7T1J2V0514919 For: 1997 GMC School Bus	10	EA.	\$ _____	\$ _____	\$ _____	\$ _____
34.1	FRONT WHEEL BEARINGS INNER W/RACE VIN#1GDM7T1J2V0514919 For: 1997 GMC School Bus	04	EA.	\$ _____	\$ _____	\$ _____	\$ _____
35.1	FRONT WHEEL BEARINGS OUTER W/RACE VIN#1GDM7T1J2V0514919 For: 1997 GMC School Bus	04	EA.	\$ N/B	\$ N/B	\$ 203.88 ext 815.52	\$ N/B
36.1	FRONT WHEEL BEARING SEAL VIN#1GDM7T1J2V0514919 For: 1997 GMC School Bus	04	EA.	\$ N/B	\$ N/B	\$ N/B	\$ N/B
37.1	TIE ROD END LEFT SIDE VIN#1GDM7T1J2V0514919 For: 1997 GMC School Bus	02	EA.	\$ N/B	\$ N/B	\$ N/B	\$ N/B
38.1	TIE ROD END RIGHT SIDE VIN#1GDM7T1J2V0514919 For: 1998 Blue Bird School Bus	02	EA.	\$ N/B	\$ N/B	\$ N/B	\$ N/B
39.1	FUEL FILTER PRIMARY VIN#1GDM7T1J2V0514919 For: 1997 GMC School Buses	10	EA.	\$ N/B	\$ N/B	\$ N/B	\$ N/B
40.1	KING PIN ASSY. VIN#1GDM7T1J2V0514919 For: 1998 GMC School Bus	04	EA.	\$ N/B	\$ N/B	\$ 1621.03 ext 4084.12	\$ N/B
41.1	DRIVE BELT VIN#1GDM7T1J2V0514919 For: 1998 GMC School Bus	05	EA.	\$ N/B	\$ N/B	\$ 44.43 ext 222.15	\$ N/B
42.1	BRAKE SLACK ADJUSTER RH FRONT VIN#1GDM7T1J2V0514919 For: 1998 GMC School Bus	04	EA.	\$ N/B	\$ N/B	\$ 431.03 ext 1724.12	\$ N/B
43.1	BRAKE SLACK ADJUSTER LH FRONT VIN#1GDM7T1J2V0514919 For: 1998 GMC School Bus	04	EA.	\$ N/B	\$ N/B	\$ 403.66 ext 1614.64	\$ N/B
44.1	BRAKE SLACK ADJUSTER RH REAR VIN#1GDM7T1J2V0514919 For: 1997 GMC School Bus	04	EA.	\$ N/B	\$ N/B	\$ 170.75 ext 683.-	\$ N/B
45.1	BRAKE SLACK ADJUSTER LH REAR VIN#1GDM7T1J2V0514919 For: 1997 GMC School Bus	04	EA.	\$ N/B	\$ N/B	\$ 170.75 ext 683.-	\$ N/B
46.1	SECONDARY FUEL FILTER Ref: #FS19596 For: 2005 Thomas Built School Bus	20	EA.	\$ N/B	\$ 29.50 ext 590.-	\$ 39.34 ext 787.20	\$ N/B
47.1	RED UNLOADING LIGHT Ref: PN#52002426 or equal For: 2005 Thomas Built School Bus	05	EA.	\$ N/B	\$ 60.84 ext 304.20	\$ 33.04 ext 165.20	\$ N/B
48.1	AMBER UNLOADING LIGHT Ref: PN#52002427 For: 2005 Thomas Built School Bus	05	EA.	\$ N/B	\$ 24.45 ext 122.25	\$ 23.89 ext 119.45	\$ N/B
49.1	HEAD LIGHT SWITCH Ref: PN#52002465 For: 2005 Thomas Built School Bus	05	EA.	\$ N/B	\$ 27.70 ext 136.-	\$ 49.35 ext 246.75	\$ N/B

ITEM NO.	DESCRIPTION	QTY.	UOM	NAPA	MIDPAC	Momico	Pac Pet
50.1	GROUP 31 12 VOLT BATTERY REGULAR POST For: All School Buses	10	EA.	\$111.61 ext 1,116.10	\$131.32 ext 1,313.20	\$178.65 ext 1,786.50	\$ N/B
51.1	BATTERY POST TERMINAL ADAPTOR (Regular Post to Studded Type) Ref. PN#728207 For: 2004-2005 Thomas Built School Bus	20	EA.	\$1.94 ext 38.80	\$2.55 ext 51.-	\$3.30 ext 66.-	\$ N/B
52.1	CABLE ACCELERATOR 61" Ref. PN#1467018 or 1668441 For: 1992 Blue Bird School Bus Vin# 1BAAGCSA4NF051488	05	EA.	\$ N/B	\$81.64 ext 408.20	\$90.- ext 450.-	\$ N/B
53.1	BALL JOINT SOCKET INTERNAL SPRING Ref. PN#1276815 For: 1992 Blue Bird School Bus Vin# 1BAAGCSA4NF051488	05	EA.	\$ N/B	\$9.60 ext 48.40	\$19.40 ext 97.-	\$ N/B
54.1	FREEZE PLUG Ref. P.N# 3922073 For: 1992 Blue Bird School Bus Vin# 1BAAGCSA4NF051488	10	EA.	\$ N/B	\$3. ext 34.60	\$5.93 ext 59.30	\$ N/B
55.1	TREADLE VALVE BRAKE Ref. P.N# 0654533 For: 1992 Blue Bird School Bus Vin# 1BAAGCSA4NF051488	05	EA.	\$ N/B	\$94.44 ext 472.20	\$104.25 ext 521.25	\$ N/B
56.1	POWER STEERING HOSE (High Pressure Side Pump to Gear Box) Ref. P.N# 1165026 For: 1998 Blue Bird School Bus	05	EA.	\$ N/B	\$51.67 ext 258.35	\$58.- ext 290.-	\$ N/B
57.1	FUEL TRANSFER PUMP ASSY. Ref. P.N#5260632 For: 2005 Thomas Built School Bus	02	EA.	\$ N/B	\$194- ext 388.-	\$244.48 ext 488.96	\$ N/B
58.1	DRIVE BELT Ref. 1GAT-K081124 For: Bluebird School Bus with International Engine	05	EA.	\$ N/B	\$45.13 ext 225.65	\$58.66 ext 293.30	\$ N/B
59.1	TURN SIGNAL SWITCH ASSY. Ref. P.N# 61200740 or 103738 For: 2004-2005 School Bus	05	EA.	\$ N/B	\$36.31 ext 181.55	\$126.79 ext 633.95	\$ N/B
60.1	BRAKE CLEANER	20	EA.	\$3.04 ext 60.80	\$ N/B	\$5.01 ext 100.20	\$ N/B
61.1	CONTACT CLEANER, ELECTRICAL	20	EA.	\$6.54 ext 130.80	\$ N/B	\$13.85 ext 277.-	\$ N/B
62.1	WD 40 LUBRICANT	20	EA.	\$3.65 ext 73.-	\$ N/B	\$13.90 ext 278.-	\$ N/B
63.1	SILICON GASKET MAKER REF: 5386342	10	EA.	\$6.10 ext 61.-	\$ N/B	\$8.90 ext 89.-	\$ N/B
64.1	ELECTRICAL TAPE	20	RL.	\$1.46 ext 29.20	\$ N/B	\$2.65 ext 52.-	\$ N/B
65.1	TEFLON PLUMBING TAPE	10	RL.	\$1.88 ext 28.80	\$ N/B	\$2.52 ext 25.20	\$ N/B
66.7	DRIVE BELT (SERPENTINE) Ref. Part# 4080790 or 3289779 For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter	05	EA.	\$ N/B	\$31.96 ext 182.30	\$66.76 ext 333.80	\$ N/B

			NAPA	MOPAC	Muncie	Pac Pet	
67.1	<b>ALTERNATOR ASSEMBLY (4 Bolts Mounting\Side)</b> LN-4943PGH or A0014943PGH or Equal For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter	02	EA.	\$ N/B	\$ 751.17 ext 1,502.34	\$ 883.96 ext 1,761.92	\$ N/B
68.1	<b>TURBO CLAMPS (3 inches) Band Type</b> For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter	10	EA.	\$ N/B	\$ N/B	\$ 61.93 ext 619.30	\$ N/B
69.1	<b>TURBO CLAMPS (4 inches) Band Type</b> For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter	10	EA.	\$ N/B	\$ N/B	\$ 26.44 ext 264.40	\$ N/B
70.1	<b>E.G.R. VALVE ASSEMBLY (EXHAUST) With Gasket</b> For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter Body I.D.# 61103-0437951-12085 Vin.# 1T88N8E2551161103 Chassis# 50270	04	EA.	\$ N/B	\$ 600.00 ext 2,400.00	\$ 696.94 ext 2,787.76	\$ N/B
71.1	<b>90 DEGREE TURBO BOOT W/Clamps (Inlet from Air Cleaner)</b> Ref.# 401079-069 For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter Body I.D.# 61103-0437951-12085 Vin.# 1T88N8E2551161103 Chassis# 50270	10	EA.	\$ N/B	\$ N/B	\$ 87.24 ext 872.40	\$ N/B
72.1	<b>UPPER RADIATOR INLET PORT (3 Bolts to Thermostat)</b> For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter Body I.D.# 61103-0437951-12085 Vin.# 1T88N8E2551161103 Chassis# 50270	04	EA.	\$ N/B	\$ N/B	\$ 50.23 ext 200.92	\$ N/B
73.1	<b>LOWER RADIATOR INLET PORT (3 Bolts to Lower Block Engine)</b> For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter Body I.D.# 61103-0437951-12085 Vin.# 1T88N8E2551161103 Chassis# 50270	04	EA.	\$ N/B	\$ N/B	\$ 49.42 ext 197.68	\$ N/B
74.1	<b>ENGINE SPEED SENSORS</b> For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter Body I.D.# 61103-0437951-12085 Vin.# 1T88N8E2551161103 Chassis# 50270	06	EA.	\$ N/B	\$ 45.88 ext 275.28	\$ 94.01 ext 564.42	\$ N/B
75.1	<b>DOOR HANDLE ASSEMBLY (OUTSIDE)</b> Ref: #64008802 For: 2005 Thomas Built School Bus Model: EFISB215 Engine: Cummins 5.9 liter Body I.D.# 61103-0437951-12085 Vin.# 1T88N8E2551161103 Chassis# 50270	10	EA.	\$ N/B	\$ N/B	\$ 33.17 ext 331.70	\$ N/B
76.1	<b>DOOR HANDEL ASSEMBLY (INSIDE)</b> Ref. # 640074310 For: 2005 Thomas Built School Bus	10	EA.	\$ N/B	\$ N/B	\$ 43.04 ext 430.40	\$ N/B

Model: EFISB215  
 Engine: Cummins 5.9 liter  
 Body I.D.# 61103-0437951-12085  
 Vin.# 1T88N8E2551161103  
 Chassis# 50270

77.1	<b>CHAIR PIVOT CYLINDER</b> (Flip Seat at side emergency door exit)	05	EA.	\$ N/B	\$ N/B	\$ N/B	\$ N/B
	For: 2005 Thomas Built School Bus						
	Model: EFISB215						
	Engine: Cummins 5.9 liter						
	Body I.D.# 61103-0437951-12085						
	Vin.# 1T88N8E2551161103						
	Chassis# 50270						
78.1	<b>ACCESSORY DOOR LOCKS\LATCHES</b> (i.e. Battery Box Door\ Electrical Panel Door)	25	EA.	\$ N/B	\$ N/B	\$ 157.20	\$ N/B
	For: 2005 Thomas Built School Bus					Off 3780.-	
	Model: EFISB215						
	Engine: Cummins 5.9 liter						
	Body I.D.# 61103-0437951-12085						
	Vin.# 1T88N8E2551161103						
	Chassis# 50270						
79.1	<b>HEATER HOSE (3/4 Inch Inner Diameter)</b> 50 feet Roll	01	Roll	\$ N/B	\$ 537.17	\$ 9.04	\$ N/B
	For: 2005 Thomas Built School Bus				Off 748.50	Off 452.-	
	Model: EFISB215						
	Engine: Cummins 5.9 liter						
	Body I.D.# 61103-0437951-12085						
	Vin.# 1T88N8E2551161103						
	Chassis# 50270						
80.1	<b>HEATER HOSE (5/8 Inch Inner Diameter)</b> 50 feet Roll	01	Roll	\$ N/B	\$ 5.35	\$ 8.79	\$ N/B
	For: 2005 Thomas Built School Bus				Off 267.50	Off 439.50	
	Model: EFISB215						
	Engine: Cummins 5.9 liter						
	Body I.D.# 61103-0437951-12085						
	Vin.# 1T88N8E2551161103						
	Chassis# 50270						
81.1	<b>FUEL LINE HOSE (3/8 Inch Inner Diameter)</b> 50 feet Roll	01	Roll	\$ N/B	\$ 2.16	\$ 2.61	\$ N/B
	For: 2005 Thomas Built School Bus				Off 108.-	Off 130.00	
	Model: EFISB215						
	Engine: Cummins 5.9 liter						
	Body I.D.# 61103-0437951-12085						
	Vin.# 1T88N8E2551161103						
	Chassis# 50270						
82.1	<b>TRANSMISSION FILTER EXTERNAL</b> Ref: PN 3342	20	EA.	\$ N/B	\$ 1.00	\$ 25.87	\$ N/B
	For: 1998 Blue Bird School Bus				Off 120.-	Off 511.60	
	Engine: Cummins 5.9 liter 190 HP						
	Body No. 189117						
	VIN. # 1BAAGCSA5TF069379						
83.1	<b>UPPER RADIATOR HOSE ASSEMBLY</b> (3pcs. Hose to Tubing to Hose)	06	EA.	\$ N/B	\$ N/B	\$ N/B	\$ N/B
	For: 1998 Blue Bird School Bus				Off 11.00	Off 11.00	
	Engine: Cummins 5.9 liter 190 HP						
	Body No. 189117						
	VIN. # 1BAAGCSA5TF069379						
84.1	<b>LOWER RADIATOR HOSE ASSEMBLY</b> (3pcs. Hose to Tubing to Hose)	06	EA.	\$ N/B	\$ N/B	\$ N/B	\$ N/B
	For: 1998 Blue Bird School Bus				Off 1.00	Off 1.00	
	Engine: Cummins 5.9 liter 190 HP						
	Body No. 189117						
	VIN. # 1BAAGCSA5TF069379						

85.1 TRANSMISSION COOLER ASSEMBLY  
 {Mounted Under Steps, Entrance)  
 For: 1998 Blue Bird School Bus  
 Engine: Cummins 5.9 liter 190 HP  
 Body No. 189117  
 VIN. # 1BAAGCSA5TF069379

ITEM NO.	DESCRIPTION	QTY.	UOM	\$ N/B	\$ N/B	\$ N/B	\$ N/B
86.1	LEAF SPRING ASSEMBLY with Bushings For: 1992 BlueBird School Bus Model: TC2000 Body No. V51142 Chassis No. 982745 VIN# 1BAAGCSA4NF051488	02	EA	\$ N/B <del>700.-</del> <del>441,400-</del>	\$ 857.38 <del>1714.76</del>	\$ N/B	
87.1	RUBBER MATTING (Flooring) SMOOTH Ref: P/N# 00854307 Thickness: .125 Length 384" x Width 39" For: 1998 GMC School Bus	06	EA	\$ N/B <del>912.76</del> <del>444,876.56</del>	\$ 3075.19 <del>18451.14</del>	\$ N/B	
88.1	RUBBER MATTING (Flooring) RIBBED Ref: P/N# 00854323 Thickness: .125 Length 384" x Width 13 1/2" For: 1998 GMC School Bus	03	EA	\$ N/B <del>485.-</del> <del>441,365.-</del>	\$ 1466.51 <del>4399.53</del>	\$ N/B	
89.1	RUBBER MATTING (Flooring) RIBBED Ref: P/N# 00854307 Thickness: .125 Length 336" x Width 38" For: 1998 Blue Bird School Bus	03	EA	\$ N/B <del>812.76</del> <del>2,438.28</del>	\$ 3075.19 <del>3075.19</del> <del>9,225.57</del>	\$ N/B	
90.1	RUBBER MATTING (Flooring) SMOOTH Ref: P/N# 00854307 Thickness: .125 Length 336" x Width 32" For: 1998 Blue Bird School Bus	03	EA	\$ N/B <del>812.76</del> <del>2,438.28</del>	\$ 3075.19 <del>9,225.57</del>	\$ N/B	
91.1	RUBBER MATTING (Flooring) RIBBED Ref: P/N# 00854323 Thickness: .125 Length 336" x Width 13 1/4" For: 1998 Blue Bird School Bus	03	EA	\$ N/B <del>485.-</del> <del>4365.-</del>	\$ 1466.51 <del>4399.53</del>	\$ N/B	
92.1	CONTACT CEMENT Ref: P/N# 04294070 For: ALL School Buses	12	EA	\$ N/B <del>196.-</del> <del>5,952.-</del>	\$ N/B <del>5,952.-</del>	\$ N/B	
93.1	HEX BOLT (Fully Threaded) Ref: 5/16 inch x 5 inch For: ALL School Buses	60	EA	\$ N/B	\$ N/B	\$ N/B	\$ N/B
94.1	FLAT WASHER Ref: 5/16 inch For: ALL School Buses	270	EA	\$ 0.09 <del>24.30</del>	\$ N/B	\$ 2.65 <del>715.50</del>	\$ N/P
95.1	DRIVE SHAFT ASSEMBLY From Trans. to rear axle For: 1992 Bluebird School Bus Vin#: 1BAAGCSA4NF051988	01	EA	\$ N/B <del>2,280.82</del> <del>ext same</del>	\$ 2954.87 <del>2954.87</del> <del>ext same</del>	\$ N/B	
96.1	MECHANICS CREEPER Heavy Duty Ref: P/N 8156246 (King crawler)	10	EA	\$ 136.- <del>1,360.-</del>	\$ N/B	\$ N/B	\$ N/B
97.1	MECHANICS STOOL W/TRAY Heavy Duty Ref: P/N 8156243	10	EA	\$ 90.- <del>900.-</del>	\$ N/B	\$ N/B	\$ N/B

98.11 DRILLBIT SET-COBALT  
Ref: P/N CD 29

02 EA \$215.- \$ N/B \$ M/B \$ M/B  
430.-

ITEM NO.	DESCRIPTION	QTY.	UOM				
99.1	1 inch ULTRA LIGHT SUPER DUTY IMPACT WRENCH WITH 6" ANVIL Ref: P/N NPT CP77806 (17 LBS) Total Weight	01	EA	\$845.- <small>ext same</small>	\$ N/B	\$ M/B	\$ M/B
100.1	JUMPER CABLES 20FT. 4 GAUGE	10	EA	\$80.- <small>800.-</small>	\$ N/B	\$ M/B	\$ M/B
101.1	1/4 inch IMPACT WRENCH Ref: P/N NPT 6-767	02	EA	\$200.- <small>400.-</small>	\$ N/B	\$ M/B	\$ M/B
102.1	DROP LIGHT HEAVY DUTY Ref: P/N SL936	10	EA	\$49.88 <small>498.80</small>	\$ N/B	\$ M/B	\$ N/B
103.1	TAP & DIE SET METRIC & STANDARD SIZE	01	EA	\$195.- <small>ext same</small>	\$ N/B	\$ M/B	\$ N/B
104.1	KING PIN INSTALLER AND REMOVER	01	EA	\$2,950.- <small>ext same</small>	\$ M/B	\$ M/B	\$ M/B
105.1	JOURNEY MAN WELDING KIT GAS	02	EA	\$344.- <small>688.-</small>	\$ N/B	\$ M/B	\$ M/B
106.1	1/2 inch DRIVE ELECTRICAL DRILL	02	EA	\$230.- <small>460.-</small>	\$ M/B	\$ M/B	\$ M/B
107.1	1/2 inch IMPACT SOCKETS	02	EA	\$83.- <small>144.</small>	\$ M/B	\$ M/B	\$ M/B
108.1	1" inch BUDD WHEEL SOCKET	02	EA	\$50.- <small>100.-</small>	\$ M/B	\$ M/B	\$ M/B
109.1	SHOP LADDER, RETRACTABLE	02	EA	\$110.- <small>220.-</small>	\$ M/B	\$ M/B	\$ M/B
110.1	COOLANT SYSTEM PRESSURE TESTER HEAVY DUTY	05	EA	\$38.- <small>190.-</small>	\$ M/B	\$ M/B	\$ M/B
111.1	MECHANIC 32 OZ. HAMMER	10	EA	\$360.- <small>360.-</small>	\$ M/B	\$ M/B	\$ M/B
112.1	SLEDGE HAMMER 5 lb.	02	EA	\$90.- <small>180.-</small>	\$ M/B	\$ M/B	\$ M/B
113.1	AIR RATCHET 3/8 DRIVE	02	EA	\$128.- <small>256.-</small>	\$ M/B	\$ M/B	\$ M/B
114.1	SOLDERING GUN W/SOLDER	01	EA	\$83.- <small>ext same</small>	\$ M/B	\$ M/B	\$ M/B
115.1	GREASE GUN PISTOL TYPE	05	EA	\$36.- <small>180.-</small>	\$ M/B	\$ M/B	\$ M/B
116.1	AIR LINE INDICATOR W/GAUGE	04	EA	\$55.- <small>220.-</small>	\$ M/B	\$ M/B	\$ M/B
117.1	WATER PUMP ASSY. For: CAT 3116 Motor 6.6 liter Vin# 1GDM7T1J2VJ514919	02	EA	\$ N/B	\$ M/B	\$ M/B	\$ M/B
118.1	VISCOUS FAN CLUTCH For: CAT 3116 Motor 6.6 liter Vin# 1GDM7T1J2VJ514919	01	EA	\$ N/B	\$ N/B	\$ M/B	\$ M/B
119.1	STEERING KNUCKLE ASSY RIGHT SIDE For: 1998 Bluebird School Bus Vin# 1GDM7T1J2VJ514919	04	EA	\$ N/B	\$ 1409.- <small>5,636.-</small>	\$ M/B	\$ M/B
120.1	STEERING KNUCKLE ASSY LEFT SIDE For: 1998 Bluebird School Bus Vin# 1GDM7T1J2VJ514919	04	EA	\$ N/B	\$ 1331.- <small>5,324.-</small>	\$ M/B	\$ M/B
121.1	LEAF SPRING ASSY FRONT Ref# 62300210 or 135168 For: 2005 Thomas Built Vin# 1T88N8E2351161133	04	EA	\$ N/B	\$ N/B	\$ 623.46 <small>2,493.84</small>	\$ M/B

122.1 LEAF SPRING ASSY REAR  
 Ref# 135172  
 For: 2005 Thomas Built  
 Vin# 1T88N8E2351161133

04 EA \$ N/B \$ N/B \$ 1057.14 \$ N/B  
 4228.56

ITEM NO.	DESCRIPTION	QTY.	UOM				
123.1	FUSE BLADE TYPE 25 AMP (5 each per box) For: 1998 Blue Bird School Bus	05	BX.	\$ 3.- 15.-	\$ N/B	\$ 3.45 17.25	\$ N/B
124.1	FUSE BLADE TYPE 30 AMP ASSY. WITH BUSHING (5 each per box) For: 1998 Blue Bird School Bus	05	BX.	\$ 3.- 15.-	\$ N/B	\$ 1.02 5.10	\$ N/B
125.1	HORN ASSY. (High) For: Blue Bird School Buses Vin# 1BAAGCSA9TF069398	05	EA.	\$ N/B 92.80	\$ 18.50	\$ 24.90 124.50	\$ N/B
126.1	HORN ASSY. (Low) For: Blue Bird School Buses Vin# 1BAAGCSA9TF069398	05	EA.	\$ N/B 92.80	\$ 18.50	\$ 24.90 124.50	\$ N/B
127.1	INJECTOR PUMP ASSY. For: 2004 Thomas Built School Bus Vin# 1T88N8D2441137570	02	EA.	\$ N/B 5,794.-	\$ 2,898.- 5,794.-	\$ 2660.- 5,320.-	\$ N/B
128.1	DIP STICK ASSY. WITH HOUSING Engine No: EFI-ISB-215 For: 2004 – 2005 Thomas Built School Buses Vin# 1T88N8E2541161111	10	EA.	\$ N/B 1,305.90	\$ 130.59	\$ 384.86 3,868.60	\$ N/B
129.1	TURN SIGNAL SWITCH ASSY. Ref#: TB-61200740 For: Thomas Built School Bus Vin# 1T88N8E2541161111	10	EA.	\$ N/B 363.40	\$ 36.31	\$ 150.03 1,500.30	\$ N/B
130.1	MARKER LIGHT RED For: 2004-2005 Thomas Built School Bus Ref#: 22019370 or equal	20	EA.	\$ N/B 88.80	\$ 4.44	\$ 4.15 83.-	\$ N/B
131.1	MARKER LIGHT, AMBER Ref#: 22020370 For: 2004-2005 Thomas Built School Bus	20	EA.	\$ N/B 88.80	\$ 4.44	\$ 3.95 79.-	\$ N/B
132.1	MARKER LIGHT CAT-EYE RED ASSY. For 1998 Blue Bird School bus Vin# 1BAAGCSA9TF069398	20	EA.	\$ N/B 131.20	\$ 6.50	\$ 5.99 119.80	\$ N/B
133.1	MARKER LIGHT CAT-EYE AMBER ASSY. For: 1998 Blue Bird School Bus	02	EA.	\$ N/B 13.54	\$ 6.77	\$ 6.47 12.94	\$ N/B
134.1	OIL FILTER Ref#: LF3972 OR EQUAL Body: F115162 Vin# 1BAAGCSA5TF069379 Model: TCFE6600S Engine# 45243433 For: 1992-1998 Blue Bird School bus	200	EA.	\$ N/B 1,578.-	\$ 7.89	\$ 9.72 19.44	\$ N/B
135.1	OIL FILTER Ref#: LF3970 For: 2004 - 2005 Thomas Built School Bus	200	EA.	\$ N/B 2,200.-	\$ 11.50	\$ 16.29 32.58	\$ N/B
136.1	P.P.-1 PARKING BRAKE VALVE W/BUTTON Ref#: 0032235 or equal For: 1998 Blue bird School Bus Vin# 1BAAGCSA5TF069379	05	EA	\$ N/B 179.90	\$ 35.98	\$ 39.85 199.25	\$ N/B
137.1	REVERSE LIGHT ASSY.	10	EA	\$ N/B 166.-	\$ 16.60	\$ 20.25 202.50	\$ N/B

Ref:#01392075 or equal  
For: 1998 Blue Bird School Bus  
Vin# 1BAAGCSA5TF069379

ITEM NO.	DESCRIPTION	QTY.	UOM				
138.1	SIDE VIEW MIRROR ASSY. For: 1998 Blue Bird School Bus Body# F115162 Vin# 1BAAGCSA5TF069379 Model: TCFE6600S Engine:# 45243433	05	EA.	\$ <u>N/B</u>	\$ 254.88	\$ 175.-	\$ <u>N/B</u>
					1,272.75	875.-	
139.1	TIE ROD END LEFT SIDE Ref# 4295283 For: 1998 Blue Bird School Bus Vin# 1BAAGCSA2WFO79694	05	EA.	\$ <u>N/B</u>	\$ 55.89	\$ 59.15	\$ <u>N/B</u>
					277.95	295.75	
140.1	TIE ROD END RIGHT SIDE Ref# 4301362 or equal For: 1998 Blue Bird School Bus Vin# 1BAAGCSA2WFO79694	25	EA.	\$ <u>N/B</u>	\$ 55.89	\$ 58.05	\$ <u>N/B</u>
					1,389.75	1451.25	
141.1	TURBO BOOT INLET 45 DEGREE ANGLE Ref# 61100101 or equal For: 2004-2005 Thomas Built School Bus	05	EA.	\$ <u>N/B</u>	\$ 188.40	\$ 173.35	\$ <u>N/B</u>
					942.-	866.75	
142.1	TURN SIGNAL ASSY. 7" For: 1998 Blue Bird School Bus	10	EA.	\$ <u>N/B</u>	\$ 22.78	\$ 23.60	\$ <u>N/B</u>
					227.80	236.50	
143.1	TURN SIGNAL FLASHER For: 1998 Blue Bird School Bus P/N: 11515961 Vin# 1BAAGCSA8TF069389	20	EA.	\$ <u>N/B</u>	\$ 12.-	\$ 11.97	\$ <u>N/B</u>
					240.-	239.40	
144.1	UNLOADING LIGHTS (RED) ASSY. Ref# 01225986 or equal For: 1998 Blue Bird School Bus	01	EA.	\$ <u>N/B</u>	\$ 25.87	\$ 29.91	\$ <u>N/B</u>
					25.87	29.91	
145.1	UNLOADING LIGHTS (AMBER) ASSY. Ref# 01225994 or equal For: 1998 Blue Bird School Bus	03	EA.	\$ <u>N/B</u>	\$ 25.87	\$ 29.91	\$ <u>N/B</u>
					77.61	89.73	
146.1	FUEL PUMP ASSY. Pump 3934242RX-M111403034B-7100 For: 1998 BLUE Bird School Bus Engine:#45587727	02	EA.	\$ <u>N/B</u>	\$ 3,700.-	\$ 3,908.75	\$ <u>N/B</u>
					7,400.-	7,817.50	
147.1	CLIP RING	40	EA.	\$ <u>N/B</u>	\$ 1.-	\$ 1.45	\$ <u>N/B</u>
					40.-	58.-	
148.1	CRANK ARM, WIPER MOTOR	06	EA.	\$ <u>N/B</u>	\$ 7.46	\$ 7.46	\$ <u>N/B</u>
					44.76	44.76	
149.1	PLUG & WIRE CONNECTOR REPAIR KIT FOR CIRCUIT BOARDS 1&2 For: 2005 Thomas Built School Bus Vin# IT88N8E2051161140 Engine MDL: EFISB215 5.9L	06	EA.	\$ <u>N/B</u>	\$ <u>N/B</u>	\$ 1101.76	\$ <u>N/B</u>
						6610.56	
150.1	GASKET FRONT TIMING COVER For: 2005 Thomas Built School Bus Vin# IT88N8E2351161133	06	EA.	\$ <u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>
151.1	SEAL, FRONT CRANKSHAFT Vin# IT88N8E2351161133	06	EA.	\$ <u>N/B</u>	\$ 27.-	\$ 36.05	\$ <u>N/B</u>
					162.-	216.30	
152.1	IDLER PULLEY ASSY. DRIVE BELT Engine MDL: EFISB215 5.9L Vin# IT88N8D2441137570	06	EA.	\$ <u>N/B</u>	\$ 61.40	\$ 196.40	\$ <u>N/B</u>
					386.44	4178.40	
153.1	TENSIONER, DRIVE BELT Engine# EFISB215 5.9L	02	EA.	\$ <u>N/B</u>	\$ 189.-	\$ 138.20	\$ <u>N/B</u>
					218.-	276.60	

Vin# IT88N8D2441137570

154.1 GREASE, HI TEMP MULTI-PURPOSE  
(5 gallon pail) 02 EA \$118.23 \$ N/B \$ N/B \$110.-  
236.46 220.-

ITEM NO.	DESCRIPTION	QTY.	UOM				
155.1	DOOR CYLINDER ASSY, PNEUMATIC For: 2004 Thomas Built School Bus Vin# IT88N8D2441137570	04	EA.	N/B	\$ 407.80 1,631.20	\$ 1,008.-	N/B
156.1	DIRECTIONAL SWITCH, PNEUMATIC DOOR Ref#: TBB-P2L-AL591ES For: 2004-2005 Thomas Built School Bus	04	EA.	N/B	\$ 12.90 51.64	\$ 16.75 67.-	N/B
157.1	SIGNAL LIGHT AMBER (SQUARE) Ref#: CE6506 or 6505 or equal For: 1998 Blue Bird School Bus VIN#1BAAGCSA9TF069217	04	EA.	N/B	\$ N/B	\$ N/B	N/B
158.1	WATER PUMP ASSY. For: International 7.3L T44E Engine:# IH1831676C92	04	EA.	N/B	\$ 340.- 1,360.-	\$ 283.50 1,139.-	N/B
159.1	RADIATOR ASSY. For: 1989-1990 Blue Bird School Bus Vin# 1BAAGCSA7LF035489	01	EA.	N/B	\$ 2,200.- ext same	\$ 1740.85 ext same	N/B
160.1	AIR CHUCK TOOL	01	EA.	11.25 ext same	\$ N/B	\$ N/B	N/B
161.1	TOOL VALVE	01	EA.	2.50 ext same	\$ N/B	\$ N/B	N/B
162.1	AIR VALVE TOOL	04	EA.	3.40 13.60	\$ N/B	\$ N/B	N/B
163.1	FILTER REGULATOR	01	EA.	94.- ext same	\$ N/B	\$ N/B	N/B
164.1	1-15/16 IMPACT SOCKET	02	EA.	35.- 70.-	\$ N/B	\$ N/B	N/B
165.1	BUDDY TIRE MOUNTING TOOL P/N: AME-71050 Mounting Tool is for 22.5 & 24.5 Tires Heavy Duty Steel Construction w/nylon Rollers to protect tire beads Total Weight: 32 lbs. (14.5kg)	02	EA.	460.- 920.-	\$ N/B	\$ N/B	M/B
166.1	SPILL MASTER OIL ABSORBANT Material (Floor Sweep) Ref#: 3110, 20# Bag	10	EA.	13.- 130.-	\$ N/B	\$ 137.85 1370.58	N/B
167.1	FRONT SHOCK ABSORBER For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	10	EA.	N/B	\$ 61.- 610.-	\$ 60.91 609.10	N/B
168.1	REAR SHOCK ABSORBER For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	10	EA.	N/B	\$ 61.- 610.-	\$ 60.91 609.10	N/B
169.1	FRONT BRAKE CHAMBER For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	06	EA.	N/B	\$ 37.61 226.02	\$ 32.- 192.00	N/B
170.1	REAR BRAKE CHAMBER For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	05	EA.	N/B	\$ 50.- 260.-	\$ 53.11 265.55	N/B
171.1	DOOR ENTRANCE ASSY. For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	02	EA.	N/B	\$ 590.- 1,180.-	\$ N/B	N/B

172.1	DOOR ENTRANCE LEVER OR PIVOT For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	02	EA.	<u>MB</u> <u>\$ 20.00</u> <u>18.-</u>	<u>\$ MB</u> <u>\$ 18.00</u>	<u>MB</u>
173.1	LOWER RADIATOR HOSE For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	06	EA.	<u>N/B</u> <u>\$ 37.00</u> <u>222.-</u>	<u>\$ 32.62</u> <u>195.72</u>	<u>MB</u>
174.1	UPPER RADIATOR HOSE For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	06	EA.	<u>N/B</u> <u>\$ 47.24</u> <u>283.44</u>	<u>\$ 47.59</u> <u>285.54</u>	<u>N/B</u>
175.1	FRONT BRAKE DRUM ASSY. For: 1999 GMC School Bus Vin# IGDM7T1JLV1514992	04	EA.	<u>N/B</u> <u>\$ 531.00</u> <u>2,124.-</u>	<u>\$ 846.31</u> <u>3,385.24</u>	<u>N/B</u>
176.1	REAR BRAKE DRUM ASSY. For: 1999 GMC School Bus Vin# IGDM7T1JLV1514992	04	EA.	<u>MB</u> <u>\$ 318.00</u> <u>1,272.-</u>	<u>\$ 231.77</u> <u>927.08</u>	<u>MB</u>
177.1	TREADLE VALVE BRAKE For: 1999 GMC School Bus Vin# IGDM7T1JLV1514992	08	EA.	<u>MB</u> <u>\$ 91.00</u> <u>755.52</u>	<u>\$ MB</u> <u>\$ 91.00</u>	<u>MR</u>
178.1	REAR SHOCK ABSORBER For: 1999 GMC School Bus Vin# IGDM7T1JLV1514992	05	EA.	<u>MB</u> <u>\$ N/B</u>	<u>\$ N/B</u>	<u>N/B</u>
179.1	FRONT TURN SIGNAL ASSY. For: 1999 GMC School Bus Vin# IGDM7T1JLV1514992	10	EA.	<u>N/B</u> <u>\$ N/B</u>	<u>\$ 202.26</u> <u>2022.60</u>	<u>MB</u>
180.1	AIR BRAKE DRYER For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	04	EA.	<u>N/B</u> <u>\$ 375.00</u> <u>1,500.-</u>	<u>\$ 213.33</u> <u>1,053.32</u>	<u>N/B</u>
181.1	DOOR SWITCH PADDLE For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	20	EA.	<u>N/B</u> <u>\$ 12.91</u> <u>258.20</u>	<u>\$ 21.54</u> <u>430.80</u>	<u>N/B</u>

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
182.1	WIPER SWITCH PADDLE For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	20	EA.	<u>N/B</u> <u>\$ 14.00</u> <u>283.-</u>	<u>\$ 25.00</u> <u>518.-</u>	<u>MB</u>
183.1	UNLOADING LIGHT SWITCH PADDLE For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	20	EA.	<u>N/B</u> <u>\$ 17.21</u> <u>344.20</u>	<u>\$ 28.27</u> <u>565.40</u>	<u>N/B</u>
184.1	DOOR LATCH LOCK For: 2005 Thomas Built School Bus Vin# 1T88N8E2551161103	20	EA.	<u>N/B</u> <u>\$ 36.56</u> <u>731.20</u>	<u>\$ 43.54</u> <u>870.80</u>	<u>N/B</u>
185.1	Air Compressor Assy. Body# V5142 Vin# 1BAAGCSA4NF051488 For: 1992 Blue Bird School Bus	01	EA.	<u>N/B</u> <u>\$ 1,000.00</u> <u>ext same</u>	<u>\$ N/B</u>	<u>N/B</u>
186.1	Back-Up Alarm Ref# 0003311 or equal For: 1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398	10	EA.	<u>N/B</u> <u>\$ 36.80</u> <u>368.-</u>	<u>\$ 46.93</u> <u>469.30</u>	<u>MB</u>
187.1	Back-Up Light Assy. w/ Bulb Ref: TB# 52000716 For: 2004-2005 Thomas Built School Bus Vin# 1T88N8E2651156217	10	EA.	<u>N/B</u> <u>\$ 11.02</u> <u>110.20</u>	<u>\$ 9.63</u> <u>96.30</u>	<u>N/B</u>
188.1	Brake Light Assy. (4 inch) For: 1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398	10	EA.	<u>N/B</u> <u>\$ 10.25</u> <u>102.50</u>	<u>\$ 12.58</u> <u>125.80</u>	<u>N/B</u>

189.1	Brake/Tail Light Assy. 7"	10	EA.	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>9.65</u>	<u>N/B</u>
	For: 2004-2005 Thomas Built School Bus Vin# 1T88N8E2651156217					<u>96.50</u>	
190.1	Switch Door Paddle	20	EA.	<u>N/B</u>	\$ <u>16.04</u>	\$ <u>190.23-17</u>	<u>N/B</u>
	Ref: TB# S2003066 For: 2004-2005 Thomas Built School Bus Vin# 1T88N8E2651156217				<u>320.80</u>	<u>463.40</u>	
191.1	Cross-Over Mirror Assy. w/Mounting Brackets	05	EA.	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>291.07</u>	<u>N/B</u>
	For: 1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398					<u>1455.35</u>	
192.1	DOOR BUZZER ALARM	05	EA.	<u>N/B</u>	\$ <u>20.20</u>	\$ <u>21.83</u>	<u>N/B</u>
	Ref: # 000214537 or equal For: 1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398				<u>101.50</u>	<u>109.15</u>	
193.1	Dimmer Switch Assy.	15	EA.	<u>N/B</u>	\$ <u>22.75</u>	\$ <u>77.62</u>	<u>N/B</u>
	For: 1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398				<u>341.25</u>	<u>1164.30</u>	
194.1	Emergency Exit Hatch Assy.	10	EA.	<u>N/B</u>	\$ <u>345.-</u>	\$ <u>441.62</u>	<u>N/B</u>
	For: 1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398				<u>3,450.-</u>	<u>4416.20</u>	
195.1	Flasher 8 way or Arial Flasher	10	EA.	<u>N/B</u>	\$ <u>118.55</u>	\$ <u>118.50</u>	<u>N/B</u>
	Ref: #01656743 For: 1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398				<u>1,085.50</u>	<u>1,185.50</u>	

ITEM NO.	DESCRIPTION	QTY.	UOM	UNIT PRICE	PRICE EXTENSION	
196.1	Flasher 8 way or Arial Flasher (For: Unloading & Stop Sign) For: 2004 Thomas Built School Bus Vin# 1T88N8D2441137570	10	EA.	<u>N/B</u>	\$ <u>108.97</u>	\$ <u>110.92</u>
					<u>1,089.70</u>	<u>1,109.20</u>
197.1	Flasher (Turn Signal) 2-Prong	10	EA.	<u>N/B</u>	\$ <u>8.20</u>	\$ <u>9.71</u>
	For: 1992 Blue Bird School Bus Vin# 1BAAGCSA4NF051488				<u>82.80</u>	<u>97.10</u>
198.1	Fuel Filter Primary	50	EA.	<u>N/B</u>	\$ <u>8.10</u>	\$ <u>12.95</u>
	Ref: # F42000 or equal For: 1992-1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398				<u>405.-</u>	<u>647.50</u>
199.1	Fuel Filter Secondary	50	EA.	<u>N/B</u>	\$ <u>37.88</u>	\$ <u>39.78</u>
	Ref: # FS19521 For: 1992-1998 Blue Bird School Bus Vin# 1BAAGCSA9TF069398				<u>1,894.-</u>	<u>1,989.-</u>
200.1	Fuel Filter Secondary	20	EA.	<u>N/B</u>	\$ <u>27.44</u>	\$ <u>20.-</u>
	Ref: #ABP-N122 - R50418 or equal For: 2004 Thomas Built School Buses				<u>448.80</u>	<u>400.-</u>
201.1	Fuse Blade Type 5 Amp (5 each per box)	05	EA.	<u>2.25</u> <u>N/B</u>	\$ <u>N/B</u>	\$ <u>1.02</u>
	For: 1998 Blue Bird School Bus				<u>11.25</u>	<u>5.10</u>
202.1	Fuse Blade Type 10 Amp (5 each per box)	05	EA.	<u>2.25</u> <u>11.25</u>	\$ <u>N/B</u>	\$ <u>1.02</u>
	VIN#1GDM7T1J2V0514919 For: 1998 Blue Bird School Bus					<u>5.10</u>
203.1	Fuse Blade Type 15 Amp (5 each per box)	05	EA.	<u>2.25</u> <u>11-25</u>	\$ <u>N/B</u>	\$ <u>1.02</u>
	For: 1998 Blue Bird School Bus					<u>5.10</u>
204.1	Upper Radiator Hose Assy.	05	EA.	<u>N/B</u>	\$ <u>16.84</u>	\$ <u>16.94</u>
	Ref: # 01341213 or equal				<u>84.20</u>	<u>84.80</u>

	For: 1992 Blue Bird School Bus					
205.1	Upper Radiator Hose assy. Ref: # 01464692 For: 1992 Blue Bird School Bus	05	EA. <u>N/B</u>	\$ <u>576.64</u> <u>263.20</u>	\$ <u>11.80</u> <u>59.-</u>	<u>N/B</u>
206.1	Upper Pipe Ref: # 1467257 or equal For: 1992 Blue Bird School Bus	05	EA. <u>N/B</u>	\$ <u>2498.83</u> <u>1,244.15</u>	\$ <u>260.-</u> <u>1300.-</u>	<u>N/B</u>
207.1	Wiper Arm Assembly Ref: # 01918572 or equal For: 1998 Blue Bird School Bus Vin# 1BAAGCSA8TF069389	20	EA. <u>N/B</u>	\$ <u>91.35</u> <u>1,927.-</u>	\$ <u>115.14</u> <u>1157.40</u>	<u>N/B</u>
208.1	Wiper Motor w/Hardware, Right Hand For: 1998 Blue Bird School Bus Vin# 1BAAGCSA8TF069389	10	EA. <u>N/B</u>	\$ <u>N/B</u>	\$ <u>141.88</u> <u>1410.80</u>	<u>N/B</u>
209.1	Wiper Motor w/Hardware, Left Hand For: 1998 Blue Bird School Bus Vin# 1BAAGCSA8TF069389	10	EA. <u>N/B</u>	\$ <u>N/B</u>	\$ <u>141.08</u> <u>1410.80</u>	<u>N/B</u>
210.1	Wiper Blades 28 inch Ref: # TB65004330 For: 2004-2005 Thomas Built School Bus	40	EA. <u>10.-</u> <u>400.-</u>	\$ <u>14.55</u> <u>582.-</u>	\$ <u>27.43</u> <u>21097.20</u>	<u>N/B</u>

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
211.1	Belt Fan For: 2004 Thomas Built School Bus Vin# 1T88N8D2441137570	10	EA. <u>N/B</u>	\$ <u>56.30</u> <u>563.-</u>	\$ <u>36.49</u> <u>364.90</u>	<u>N/B</u>
212.1	Switch Turn Signal Assembly Ref: P.N. # 1033738 For: 2004-2005 Thomas Built School Bus	10	EA. <u>N/B</u>	\$ <u>36.31</u> <u>363.10</u>	\$ <u>142.80</u> <u>1428.-</u>	<u>N/B</u>
213.1	Switch Rocker Door Ref. P.N. # 52003110 For: 2004-2005 Thomas Built School Bus	20	EA. <u>N/B</u>	\$ <u>16.30</u> <u>327.20</u>	\$ <u>18.15</u> <u>363.-</u>	<u>N/B</u>
214.1	Radiator Cap Ref. P.N. # 1453265 For: 1992 Blue Bird School Bus	05	EA. <u>N/B</u>	\$ <u>9.35</u> <u>46.75</u>	\$ <u>8.91</u> <u>44.58</u>	<u>N/B</u>
215.1	Gasket Valve Cover Ref: P.N. # 3930906 For: 1992 Blue Bird School Bus	20	EA. <u>N/B</u>	\$ <u>4.50</u> <u>90.-</u>	\$ <u>8.50</u> <u>170.-</u>	<u>N/B</u>
216.1	Engine Mount, Rear Ref: # 10008300 For: P.N. # 10008300 Vin# 1BAAGCSA4NF051488	10	EA. <u>N/B</u>	\$ <u>20.45</u> <u>209.50</u>	\$ <u>24.27</u> <u>242.70</u>	<u>N/B</u>
217.1	Gasket Gear Cover Ref: P.N. # 3918673 For: 1998 Blue Bird School Bus Vin# 1BAAGCSA4NF051488	06	EA. <u>N/B</u>	\$ <u>33.35</u> <u>200.10</u>	\$ <u>41.60</u> <u>249.60</u>	<u>N/B</u>
218.1	Air Governor Ref: P.N. # 275491 For: 1992 Blue Bird School Bus	10	EA. <u>N/B</u>	\$ <u>37.62</u> <u>376.-</u>	\$ <u>28.08</u> <u>280.80</u>	<u>N/B</u>
219.1	Oil, 15-40wt Engine Oil	10	DR. <u>630.98</u> <u>6309.80</u>	\$ <u>N/B</u>	\$ <u>6.74</u> <u>6,740.00</u>	<u>650.0</u> <u>6,500.-</u>
220.1	Light Bulb Ref: # 194 or equal	20	BX. <u>3.60</u> <u>72.00</u>	\$ <u>N/B</u>	\$ <u>4.00</u> <u>80.00</u>	<u>N/B</u>
221.1	Light Bulb Ref: # 1156	40	BX. <u>4.00</u> <u>160.00</u>	\$ <u>N/B</u>	\$ <u>6.50</u> <u>260</u>	<u>N/B</u>
222.1	Light Bulb Ref: # 1157 or equal	40	BX. <u>3.50</u> <u>140.00</u>	\$ <u>N/B</u>	\$ <u>4.25</u> <u>170.00</u>	<u>N/B</u>

223.1	Circuit Breaker Box Ref: # 151279 (Board) or equal For: 2005 Thomas Built School Bus Vin# 1T88N8E2351161133	05	EA.	<u>N/B</u>	\$ <u>251.60</u>	\$ <u>251.57</u>	<u>N/B</u>
224.1	Circuit Breaker Box Ref: # 151280 (Board) or equal For: 2005 Thomas Built School Bus Vin# 1T88N8E2351161133	05	EA.	<u>N/B</u>	\$ <u>251.21</u>	\$ <u>251.57</u>	<u>N/B</u>
225.1	Transmission Filter Internal For: 2004-2005 Thomas Built School Bus Vin# 1T88N8E2351161133	50	EA.	<u>N/B</u>	\$ <u>35.00</u>	\$ <u>295.75</u>	<u>N/B</u>
226.1	Transmission Filter External For: 2004-2005 Thomas Built School Bus Vin# 1T88N8E2351161133	50	EA.	<u>N/B</u>	\$ <u>13.00</u>	\$ <u>18.89</u>	<u>N/B</u>

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
227.1	Turbo Assembly For: 2004 Thomas Built School Bus Vin# 1T88ND2441137570	05	EA.	<u>N/B</u>	\$ <u>1900.00</u>	\$ <u>2079.01</u>
					<u>9500.00</u>	<u>10,395.05</u>
228.1	Turbo assembly For: 1998 Blue Bird Bus Body # F115162 Model # TCFE6600S Vin# 1BAAGCSA5TF169379 Engine # 45243433	05	EA.	<u>N/B</u>	\$ <u>1177.00</u>	\$ <u>1033.56</u>
					<u>5895.00</u>	<u>8167.80</u>
229.1	Wiper Arm Pantograph Assembly Ref: # TB-65005642 For: 2004-2005 Thomas Built School Bus	20	EA.	<u>N/B</u>	\$ <u>45.00</u>	\$ <u>86.96</u>
					<u>900.00</u>	<u>1739.20</u>
230.1	Radiator Assembly w/Cap Ref: # 62570527 For: 2004-2005 Thomas Built School Bus Vin# 1T88N8E2351161133	02	EA.	<u>N/B</u>	\$ <u>3576.00</u>	\$ <u>3416.77</u>
					<u>7152.00</u>	<u>6833.54</u>
231.1	Radiator Assembly w/Cap Ref: # 1769470 For: 1996-1998 Blue Bird School Bus Body# F115162 Model# TCFE6600S Vin# 1BAAGCSA5TF069379 Engine# 45243433	02	EA.	<u>N/B</u>	\$ <u>2361.00</u>	\$ <u>1453.53</u>
					<u>4722.00</u>	<u>2907.06</u>
232.1	Radiator Assembly w/Cap Ref: # 1458744 For: 1992 Blue Bird School Bus Body# V5142 For: 1996-1998 Blue Bird School Bus Vin# 1BAAGCSA4NF051488	01	EA.	<u>N/B</u>	\$ <u>1650.00</u>	\$ <u>1740.85</u>
					<u>1650.00</u>	<u>1740.85</u>
233.1	Tie Rod End, Left For: 2005 Thomas Built School Bus Vin# 1T88n8E2351161133	05	EA.	<u>N/B</u>	\$ <u>87.42</u>	\$ <u>131.86</u>
					<u>439.10</u>	<u>659.30</u>
234.1	Tie Rod End, Right For: 2005 Thomas Built School Bus Vin# 1T88n8E2351161133	05	EA.	<u>N/B</u>	\$ <u>92.77</u>	\$ <u>144.50</u>
					<u>463.85</u>	<u>722.50</u>
235.1	Oil Filter Ref: # 7600 B-76 For: 1998 GMC School Bus Vin# 10DM7TIJ2VJ514919	20	EA.	<u>N/B</u>	\$ <u>8.50</u>	\$ <u>12.59</u>
					<u>170.00</u>	<u>251.80</u>
236.1	Oil Filter Ref: # B7039 For: 1998 International School Bus	20	EA.	<u>N/B</u>	\$ <u>13.71</u>	\$ <u>19.29</u>
					<u>274.20</u>	<u>385.80</u>

237.1	Automatic Transmission Fluid (ATF) 55 Gallon Drum	15	DR. <u>594.11</u> <u>8,941.65</u>	\$ <u>N/B</u> <u>464.11</u>	<u>777.75</u> <u>464.11</u>	<u>464.11</u> <u>6,960.00</u>
238.1	Drive Belt, Serpentine Ref: # P.N. # 4080595 For: 1998 Blue Bird School Bus Body# F11S162 Model# TCFE6600S Vin# 1BAAGCSA5TF069379 Engine# 45243433	05	EA. <u>M/B</u>	\$ <u>N/B</u> <u>58.29</u>	<u>58.29</u> <u>276.45</u>	<u>N/B</u>

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT EXTENSION	PRICE
239.1	Switch, Stop Light For: 1998 Blue Bird School Bus Body# F11S162 Model# TCFE6600S Vin# 1BAAGCSA5TF069379 Engine# 45243433	10	EA. <u>N/B</u>	\$ <u>41.11</u> <u>410.11</u>	<u>41.11</u> <u>410.11</u>	<u>416.99</u> <u>410.11</u>
240.1	Tank Reservoir Coolant Ref: # 1769488 For: 1998 Blue Bird School Bus Vin# 1BAAGCSA5TF069379	05	EA. <u>M/B</u>	\$ <u>389.11</u> <u>1,945.11</u>	<u>389.11</u> <u>1,945.11</u>	<u>410.95</u> <u>2,054.75</u>
241.1	Cap Hub Ref: # CR1703 For: 1998 Blue Bird School Bus Vin# 1BAAGCSA5TF069379	10	EA. <u>M/B</u>	\$ <u>28.50</u> <u>285.00</u>	<u>28.50</u> <u>285.00</u>	<u>33.29</u> <u>332.90</u>
242.1	Headlight Assembly Ref: # P.N. # 6054 For: 1998 Blue Bird School Bus	20	EA <u>9.50</u> <u>190.00</u>	\$ <u>N/B</u>	<u>9.61</u> <u>192.20</u>	<u>M/B</u>
243.1	Automatic Transmission w/ Torque Converter (AT-545) For: 1998 Blue Bird School Bus	02	EA <u>N/B</u>	\$ <u>2,600.00</u> <u>5,300.00</u>	\$ <u>N/B</u>	<u>N/B</u>
244.1	Fuel Filter Bowl for Filter FS19521 Ref: # RR30063 Vin# 1BAAGCSA9TF069398	02	EA <u>M/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	<u>N/B</u>
245.1	Radiator Assembly Vin# 1GDM7T1514959 For: 1998 Blue Bird School Bus GMC Engine Type CAT 3116	02	EA <u>M/B</u>	\$ <u>N/B</u>	\$ <u>2,805.11</u> <u>5,610.11</u>	<u>N/B</u>
246.1	Radiator Assembly Vin# 1HVBABNIWH572880 For: 1998 Blue Bird School Bus Engine Family: WNUXH0444FNA 7.3L T444E (3800)	01	EA <u>M/B</u>	\$ <u>1,451.11</u> <u>1,451.11</u>	\$ <u>1,233.95</u> <u>ext same</u>	<u>M/B</u>
247.1	Brake Shoes, Front Ref: # TH1308RRMA For: 1992 Blue Bird School Bus	20	EA <u>N/B</u>	\$ <u>47.11</u> <u>940.11</u>	\$ <u>93.11</u> <u>1,860.11</u>	<u>N/B</u>
248.1	Brake Shoes, Rear Ref: # CRLBE4515Q21 For: 1992 Blue Bird School Bus	20	EA <u>N/B</u>	\$ <u>86.11</u> <u>1,720.11</u>	\$ <u>53.11</u> <u>1,060.11</u>	<u>f</u>
249.1	Center Support Bearing, Driveshaft For: 1998 Blue Bird School Bus Vin# 1BAAGCSA5TF069379 Engine: TCFE2000 5.9L	06	EA <u>N/B</u>	\$ <u>102.11</u> <u>600.11</u>	\$ <u>137.34</u> <u>824.14</u>	<u>f</u>
250.1	Front Brake Drums For: 1998 International Bus Vin# 1HVBABN1WH572877	04	EA <u>N/B</u>	\$ <u>225.63</u> <u>902.52</u>	\$ <u>205.11</u> <u>820.11</u>	<u>f</u>
251.1	Rear Brake Drums	04	EA <u>N/B</u>	\$ <u>260.00</u> <u>1,040.00</u>	\$ <u>257.99</u> <u>1,031.94</u>	<u>f</u>

For: 1998 International Bus  
Vin# 1HVBABN1WH572877

252.1 Turn Signal Assembly, Front  
For: 1998 International Bus  
Vin# 1HVBABN1WH572877

06 EA 5/B \$128.- 768.- \$113.45 680.70 N/B

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
253.1	Transmission Wiring Harness (Back of Transmission) Plug SN# 6310279782 For: 2004 Thomas Built School Bus Vin# 1T88N8D2641137568 Trans. Model# AD2000	05	EA	<u>M/B</u> \$75.- 375.-		<u>\$1,311.23</u> <u>6556.15</u>
254.1	Fan Clutch Assembly Ref: Part# CU3927735 For: 2005 Thomas Built School Bus Vin# 1T88N8E2251161138	04	EA			<u>\$117.31</u> <u>4,469.24</u>
255.1	Brake Drum Front Ref: Part # 65651B For: 1996 Blue Bird School Bus Vin# 1BAAGCSA1TF069377	06	EA			<u>\$413.37</u> <u>2,490.22</u>
256.1	Brake Drum Rear Ref: Part # 656708 For: 1996 Blue Bird School Bus Vin# 1BAAGCSA1TF069377	10	EA			<u>\$430.50</u> <u>4305.60</u>
257.1	U-Joint Ref: Part# 5188X For: 1996 Blue Bird School Bus Vin# 1BAAGCSA1TF069377	08	EA			<u>\$37.75</u> <u>302.-</u>
258.1	Slack Adjuster 10 spline Ref: Part# 1EUC-KN47001 For: 1996 Blue Bird School Bus Vin# 1BAAGCSA1TF069377	08	EA			<u>\$32.62</u> <u>260.95</u>
259.1	Transmitter Ref: Part# 1EUC-KN47001 For: 1999 International School Bus Vin# 1BAAGCSA1TF069377	03	EA			<u>\$353.68</u> <u>1061.04</u>
260.1	Turn Signal Switch For: 1999 International School Bus Vin# 1HVBABN1WH572880	01	EA			<u>\$10.35</u> <u>ext same</u>
261.1	Left Front Leaf Spring Shock Mount Bracket02 For: 1996 / 1998	EA				<u>\$152.41</u> <u>304.82</u>
262.1	Right Front Leaf Spring Shock Mount Bracket For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	02	EA			<u>\$152.41</u> <u>304.82</u>
263.1	Left Rear Leaf Spring Shock Mount Bracket 02 For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	EA				<u>\$171.25</u> <u>342.50</u>
264.1	Right Rear Leaf Spring Shock Mount Bracket For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	02	EA			<u>\$171.25</u> <u>342.50</u>
265.1	Front Shock Absorbers Heavy Duty For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	20	EA			<u>\$74.12</u> <u>1482.40</u>
266.1	Rear Shock Absorbers Heavy Duty For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	20	EA	<u>M/B</u> \$130.- 2,600.-		<u>\$72.92</u> <u>1458.40</u> <u>N/B</u>

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
267.1	Rear Inner Axle Seal For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	05	EA	\$ 40.- 225.-	\$ 58.20 274.-	N/B
268.1	Alternator Assembly with Pulley For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	02	EA	\$ 650.- 1,300.-	\$ 593.82 1,187.64	
269.1	Front Timing Cover Assembly w/Gasket For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	02	EA	\$ 160.- 320.-	\$ 208.14 416.28	
270.1	Front Timing Cover Crank Shaft Seal For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	02	EA	\$ 60.- 120.-	\$ 141.80 283.60	
271.1	Front Inner Axle Seal For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	05	EA	\$ 34.22 171.10	\$ 48.23 241.15	
272.1	Alternator Assembly with Pulley For: 2005 Thomas Built School Bus Vin# 1T88N8E2051161140	02	EA	\$ 853.- 1,700.-	\$ 934.05 1,868.10	
273.1	Left Front Leaf Spring Shock Mount Bracket 02 For: 2005 Thomas Built School Bus Vin# 1T88N8E2051161140	EA		\$ 120.- 240.-	\$ 137.84 275.68	
274.1	Right Front Leaf Spring Shock Mount Bracket For: 2005 Thomas Built School Bus Vin# 1T88N8E2051161140	02	EA	\$ 170.- 240.-	\$ 137.84 275.68	
275.1	Right Rear Leaf Spring Shock Mount Bracket For: 2005 Thomas Built School Bus Vin# 1T88N8E2051161140	02	EA	\$ 169.- 138.-	\$ 181.25 362.50	
276.1	Left Rear Leaf Spring Shock Mount Bracket 02 For: 2005 Thomas Built School Bus Vin# 1T88N8E2051161140	EA		\$ 60.- 138.-	\$ 181.25 362.50	
277.1	Front Hub Inner Axle Seal Mount For: 2005 Thomas Built Bus Vin# 1T88N8E2051161140	05	EA	\$ 38.00 70.25	\$ 51.38 256.90	
278.1	Rear Hub Inner Axle Seal Mount For: 2005 Thomas Built Bus Vin# 1T88N8E2051161140	05	EA	\$ 49.44 220.85	\$ 66.12 330.60	
279.1	Alternator Assembly	04	EA	\$ 230.- 920.-	\$ N/B	
280.1	Tensioner Belt	10	EA	\$ 125.- 1,250.-	\$ 147.70 1,477.-	
281.1	Alternator Assy. 4 bolts Side Mount	04	EA	\$ 853.- 3,412.-	\$ 756.99 3,027.46	
280.1	Tensioner Belt	10	EA	\$ 109.- 1,090.-	\$ 135.23 1,352.30	
281.1	Front Timing Case w/Gasket For: 1996/1998 Blue Bird School Bus Vin# 1BAAGCSAXWF079698	02	EA	\$ 300.- 600.-	\$ 554.82 409.64	
282.1	Drive Belt Ref: P.N. # 3289779 or 4080790 or equal For: 2005 Thomas Built School Bus	20	EA	\$ 36.40 729.20	\$ 89.15 1,783.-	N/B

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
283.1	Circuit Board # 1 Ref: P.N. # 151279 For: 2005 Thomas Built School Bus	10	EA	\$ 250.00 2,596.-	\$ 255.- 2,550.-	N/B

284.1	Circuit Board # 2 Ref: P.N. # 151280 For: 2005 Thomas Built School Bus	10	EA	<u>N/B</u>	\$ <u>250.00</u> <u>2511.20</u>	\$ <u>267.53</u> <u>2675.30</u>	<u>N/B</u>
285.1	Fuel Pump Assembly Injector Ref: P.N. # 5264245NX For: 2005 Thomas Built School Bus	01	EA		\$ <u>800.00</u> <u>ext same</u>	\$ <u>35.00</u> <u>35.00</u>	
286.1	Front Wheel Bearings Inner w/Race For: 2004-2005 Thomas Built School Bus Vin# 1T88N8D2641137568	10	EA		\$ <u>39.36</u> <u>393.60</u>	\$ <u>119.00</u> <u>1190.00</u>	
287.1	Amber Unloading Light Ref: P.N. # 52002465 or equal For: 2005 GMC School Bus	20	EA	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
288.1	Mechanics Creeper King Crawler Heavy Duty	10	EA	<u>136.00</u> <u>1,360.00</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
289.1	Mechanics Creeper Seat w/Tray	02	EA	<u>90.00</u> <u>180.00</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
290.1	Cobalt Drill Bit Set	02	EA	<u>215.00</u> <u>430.00</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
291.1	1" Ultra-Light Super Duty Impact Wrench w/6" Anvil	01	EA	<u>845.00</u> <u>ext same</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
292.1	1/2" Drive Impact Gun	02	EA	<u>200.00</u> <u>400.00</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
293.1	75 Piece MET/SAE Tap and Die Set	01	EA	<u>195.00</u> <u>ext same</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
294.1	OTC King Pin Remover & Installer	01	EA	<u>2,950.00</u> <u>ext same</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
295.1	Journeyman Welding Kit Gas	02	EA	<u>344.00</u> <u>688.00</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
296.1	1/2" Electric Drill Heavy Duty	01	EA	<u>230.00</u> <u>ext same</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
297.1	ENGINE MOUNT ASSY. For: 2005 Thomas Built School Bus Ref: 62231628	06	EA	<u>N/B</u>	\$ <u>410.00</u> <u>2,460.00</u>	\$ <u>230.39</u> <u>1,382.34</u>	
298.1	ENGINE MOUNT BUSHING/PAD For: 2005 Thomas Built School Bus Ref: 61230271	06	EA	<u>N/B</u>	\$ <u>70.00</u> <u>420.00</u>	\$ <u>87.62</u> <u>525.72</u>	
299.1	LOW COOLANT SENSOR For: 2005 Thomas Built School Bus Ref: 61201462	10	EA	<u>N/B</u>	\$ <u>21.00</u> <u>210.00</u>	\$ <u>20.70</u> <u>207.00</u>	
300.1	ACCELERATOR PEDAL ELECTRONIC For: 2005 Thomas Built School Bus Ref: 61150124	01	EA	<u>N/B</u>	\$ <u>405.00</u> <u>ext same</u>	\$ <u>4246.73</u> <u>ext same</u>	
301.1	Switch Momentary P/N: 52004992 For 2004-05 Thomas Built Bus VIN: 1T88N8D2541137559	20	EA	<u>N/B</u>	\$ <u>7.16</u> <u>143.20</u>	\$ <u>10.58</u> <u>211.00</u>	
302.1	Buzzer, W/ Jam nut P/N: 52004023 For 2004-05 Thomas Built Bus VIN: 1T88N8D2541137559	20	EA	<u>N/B</u>	\$ <u>64.28</u> <u>1,285.60</u>	\$ <u>74.39</u> <u>1,487.80</u>	<u>N/B</u>

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION	
303.1	Front Brake Drums P/N: DB1655B For 2004-05 Thomas Built Bus VIN: 1T88N8D2541137559	08	EA	<u>N/B</u>	\$ <u>253.63</u> <u>2,029.04</u>	\$ <u>498.39</u> <u>3,987.12</u>	<u>N/B</u>
304.1	Rear Brake Drums P/N: DB1657B For 2004-05 Thomas Built Bus VIN: 1T88N8D2541137559	08	EA	<u>N/B</u>	\$ <u>150.00</u> <u>1,248.00</u>	\$ <u>1491.72</u> <u>1,933.76</u>	
305.1	Air Compressor Assembly	02	EA	<u>N/B</u>	\$ <u>1,000.00</u> <u>2,000.00</u>	\$ <u>N/B</u>	<u>N/B</u>

For: 1998 Blue Bird School Bus

VIN: 1BAAGCSA2WF079694

P/N: 3558082 Ser: 2J2695M391

Holset SS296BE E-Type

306.1	Emergency Switch window IC P/N: 450103001 For: 2004-2005 Thomas Built School Buses	40	EA.	<u>N/B</u>	\$ <u>100.19</u> <u>5767.60</u>	\$ <u>186.80</u> <u>74960.00</u>	<u>N/B</u>
307.1	Emergency window Switch Ref: PN# 45003571 For: 2004-05 Thomas Built School Bus	40	EA.	<u>N/B</u>	\$ <u>11.00</u> <u>482.00</u>	\$ <u>13.20</u> <u>530.40</u>	
308.1	Emergency window Switch/Handle Kit P/N: THSP21101 For: 2004-05 Thomas Built School Bus	40	EA.	<u>N/B</u>	\$ <u>16.40</u> <u>678.40</u>	\$ <u>N/B</u>	
309.1	Drive Belt P/N: 4080790 or equal to For: 2005 Thomas Built Bus	20	EA.	<u>N/B</u>	\$ <u>36.40</u> <u>729.20</u>	\$ <u>44.71</u> <u>894.20</u>	
310.1	Wiper Link P/N: 25357061	20	EA.	<u>N/B</u>	\$ <u>17.47</u> <u>349.40</u>	\$ <u>27.53</u> <u>550.60</u>	
311.1	Wiper Link P/N: 85650401	20	EA.	<u>N/B</u>	\$ <u>9.10</u> <u>182.00</u>	\$ <u>13.17</u> <u>263.40</u>	
312.1	Driver Wiper P/N: 85650059	20	EA.	<u>N/B</u>	\$ <u>2.08</u> <u>41.60</u>	\$ <u>N/B</u>	
313.1	Pivot Plate wiper P/N.65004328	20	EA.	<u>N/B</u>	\$ <u>10.86</u> <u>371.20</u>	\$ <u>N/B</u>	
314.1	Bepper /Buzzer P/N: BUZ0102	20	EA.	<u>N/B</u>	\$ <u>6.78</u> <u>1285.60</u>	\$ <u>N/B</u>	
315.1	Switch Turn Signal & Dimmer P/N48282	20	EA.	<u>N/B</u>	\$ <u>82.00</u> <u>1,640.00</u>	\$ <u>116.79</u> <u>2,335.80</u>	
316.1	Flex Hose 90% W clamps P/N/ 62192134	20	EA.	<u>N/B</u>	\$ <u>129.93</u> <u>2,598.60</u>	\$ <u>149.04</u> <u>298.80</u>	
317.1	Compressor Head Gasket P/N: 4920062 For: 1998 Blue Bird Bus VIN: 1BAAGCSA2WF079694	05	EA.	<u>N/B</u>	\$ <u>8.00</u> <u>40.00</u>	\$ <u>11.57</u> <u>57.85</u>	
318.1	Simple Green Cleaner (55gal drums) None Corrosive/ bio degradable	05	DR.	<u>993.00</u> <u>4,965.00</u>	\$ <u>N/B</u>	\$ <u>105.65</u> <u>528.25</u>	
319.1	Tie- Rod End RH P/N: MBA 6073382110 TRW For: 2005 Thomas Built School Bus	06	EA.	<u>N/B</u>	\$ <u>92.83</u> <u>556.98</u>	\$ <u>166.20</u> <u>637.20</u>	
320.1	Tie-Rod End LH. P/N: MBA 6073380710 TRW For: 2005 Thomas Built School Bus	06	EA.	<u>N/B</u>	\$ <u>92.83</u> <u>556.98</u>	\$ <u>106.20</u> <u>637.20</u>	<u>N/B</u>

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
321.1	Drag Link Assembly (steering Link) VIN#1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus	10	EA.	<u>N/B</u> <u>431.00</u> <u>4,003.10</u>	\$ <u>431.00</u> <u>4,003.10</u>	\$ <u>492.99</u> <u>4,929.90</u>
322.1	Hose CAC Right Side VIN: 1T88N8E2251156229 For: 2004-2005 School Bus	05	EA.	<u>N/B</u> <u>18.90</u> <u>94.95</u>	\$ <u>18.90</u> <u>94.95</u>	\$ <u>57.90</u> <u>289.80</u>
323.1	Hose CAC Left Side VIN#1T88N8E2251156229 For: 2004-2005 Thomas Built School Bus P/N# 62192133	05	EA.	<u>N/B</u> <u>24.91</u> <u>174.55</u>	\$ <u>24.91</u> <u>174.55</u>	\$ <u>56.70</u> <u>283.80</u>
324.1	Hose CAC Lower VIN#1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus P/N: 62192134	05	EA.	<u>N/B</u> <u>89.37</u> <u>446.35</u>	\$ <u>89.37</u> <u>446.35</u>	\$ <u>142.32</u> <u>711.60</u>

325.1	Hose Clamps (HUMP type) VIN#1T88N8D2641137568 For: 2004-2005 Thomas Built School Bus	20	EA.	<u>M/B</u>	\$ <u>M/B</u>	\$ <u>26.24</u> <u>524.20</u>	<u>M/B</u>
326.1	BRAKE Shoes Rear P/N: GE 4709 ESG For: 1998 Blue Bird Bus VIN: 1BAAGCSA2WF079694	40	EA.	<u>M/B</u>	\$ <u>10.54</u> <u>4821.60</u>	\$ <u>407.-</u> <u>18,680.-</u>	
327.1	Brake Shoes Front P/N: ASMA 2124719E For: 1998 Blue Bird Bus School Buses VIN: 1BAAGCSA2WF079694	40	EA.	<u>M/B</u>	\$ <u>15.57</u> <u>51400.-</u>	\$ <u>349.67</u> <u>13,986.80</u>	
328.1	Ignition Assembly W/Keys VIN#1T88N8D2641137568 For: 2004-2005 Thomas Built School Buses	10	EA.	<u>M/B</u>	\$ <u>26.48</u> <u>2666.80</u>	\$ <u>43.63</u> <u>436.30</u>	
329.1	Universal Turn Signal Switch With Wire connector P/N: 48282X	10	EA.	<u>M/B</u>	\$ <u>82.-</u> <u>820.-</u>	\$ <u>43.63</u> <u>436.30</u>	
330.1	Turbo Assembly P/N: 4089314 NX For 2005 Thomas Built Bus VIN: 1T88N8D2541137559	04	EA.	<u>M/B</u>	\$ <u>1,900.-</u> <u>7,600.-</u>	\$ <u>2,361.71</u> <u>94446.84</u>	
331.1	Brake Hose Front (air) 24" lenght VIN#1T88N8D2641137568 For: 2004-2005 Thomas Built School Buses	10	EA	<u>M/B</u>	\$ <u>18.54</u> <u>188.40</u>	\$ <u>152.70</u> <u>1,527.-</u>	
332.1	FUEL Pressure Regulator. VIN#1T88N8D2541137559 For: 2005 Thomas Built School Buses	06	EA	<u>M/B</u>	\$ <u>M/B</u>	\$ <u>M/B</u>	
333.1	Push Pull Switch 2-Prong P/N: 1120765	20	EA.	<u>M/B</u>	\$ <u>28.31</u> <u>506.20</u>	\$ <u>6.62</u> <u>132.40</u>	
334.1	Push Pull Switch 4-Prong P/N: 0367466	20	EA.	<u>M/B</u>	\$ <u>M/B</u>	\$ <u>29.56</u> <u>591.20</u>	
335.1	Butt Connectors 22-18 AWG	10	BX.	<u>4.50</u> <u>45-</u>	\$ <u>M/B</u>	\$ <u>6.73</u> <u>67.30</u>	
336.1	Butt Connectors 16-14 AWG	10	BX.	<u>5.30</u> <u>5200-mm</u>	\$ <u>M/B</u>	\$ <u>8.06</u> <u>80.60</u>	

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
337.1	Butt Connectors 12-10 AWG VIN#1GDM7T1J2V0514919 For: 1997 GMC School Bus	10	BX.	<u>6.50</u> <u>65-</u>	\$ <u>M/B</u>	\$ <u>11.09</u> <u>110.90</u>
338.1	Wire Roll 18 Gauge (Automotive wire)	03	Rolls	<u>12.-</u> <u>36.00</u>	\$ <u>M/B</u>	\$ <u>6.28</u> <u>18.84</u>
339.1	Female Connector 22-18 AWG	10	BX.	<u>30.00</u> <u>300.00</u>	\$ <u>M/B</u>	\$ <u>7.84</u> <u>78.40</u>
340.1	Female Connector 16-14 AWG	10	BX.	<u>30.-</u> <u>300.-</u>	\$ <u>M/B</u>	\$ <u>7.84</u> <u>78.40</u>
341.1	Female Connectors 12-10 AWG	10	BX.	<u>14.-</u> <u>140.-</u>	\$ <u>M/B</u>	\$ <u>8.65</u> <u>86.50</u>
342.1	Toggle Switch 2-Prong	10	EA.	<u>M/B</u>	\$ <u>M/B</u>	\$ <u>5.50</u> <u>55-</u>
343.1	BRAKE SLACK ADJUSTER LH FRONT VIN#1GDM7T1J2V0514919 For: 1998 GMC School Bus	04	EA.	<u>M/B</u>	\$ <u>M/B</u>	\$ <u>M/B</u>
344.1	Valve Safety release P/N: 284142N	20	EA.	<u>M/B</u>	\$ <u>20.-</u> <u>400.-</u>	\$ <u>15.64</u> <u>312.80</u>
345.1	Wire 16-Gauge (automotive)	03	Rolls	<u>21.-</u> <u>63.-</u>	\$ <u>M/B</u>	\$ <u>6.25</u> <u>18.75</u>
346.1	Wire 12 gauge (automotive)	03	ROLLS	<u>38.-</u> <u>114.-</u>	\$ <u>M/B</u>	\$ <u>27.48</u> <u>82.44</u>

347.1	Male Connectors 22-18 AWG	10	BX.	<u>24-</u> <u>240-</u>	\$ <u>M/B</u>	\$ <u>6.60</u>	<u>M/B</u>
348.1	Male Connector 16-14 AWG	10	BX.	<u>15-</u> <u>150-</u>	\$ <u>M/B</u>	\$ <u>6.60</u>	<u>M/B</u>
349.1	Wire 22- Gauge Ref: PN#52002465 For: 2005 Thomas Built School Bus	03	ROLLS	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
350.1	Hose Clamps 5/16"	30	EA.	<u>0.66</u> <u>19.80</u>	\$ <u>N/B</u>	\$ <u>0.34</u> <u>10.80</u>	
351.1	Hose Clamps 3/8"	30	EA.	<u>0.81</u> <u>24.30</u>	\$ <u>N/B</u>	\$ <u>0.43</u> <u>12.90</u>	
352.1	Hose Clamps 1"	30	EA.	<u>1-</u> <u>30-</u>	\$ <u>M/B</u>	\$ <u>0.44</u> <u>13.20</u>	
353.1	Hose Clamps 2"- 2 1/2" Ref. PN#1276815 For: 1992 Blue Bird School Bus Vin# 1BAAGCSA4NF051488	30	EA.	<u>1.90</u> <u>57-</u>	\$ <u>N/B</u>	\$ <u>0.58</u> <u>17.40</u>	
354.1	Hose Clamps 3"	30	EA.	<u>1.31</u> <u>39.30</u>	\$ <u>M/B</u>	\$ <u>0.68</u> <u>20.40</u>	
355.1	Quick Connect Coupling (air) 1/2"	20	EA.	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
356.1	Quick Connect coupling (air) 3/8"	20	EA.	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
357.1	Quick Connect Coupling (air) 1/4"	20	EA.	<u>6-</u> <u>120-</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
358.1	Quick Connect Coupling (air) 9/16"	20	EA.	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	
359.1	Light Bulb P/N 1004	20	BX.	<u>7.50</u> <u>150-</u>	\$ <u>N/B</u>	\$ <u>2.49</u> <u>49.80</u>	
360.1	Light Bulb P/N: H-3	20	BX.	<u>3.32</u> <u>66.40</u>	\$ <u>N/B</u>	\$ <u>0.17</u> <u>4.04</u>	
361.1	Air Compressor Assembly For 1992 Blue Bird Bus VIN: 1BAAGCSA5NF049085 Engine # EIN049085	01	EA.	<u>N/B</u> <u>ext same</u>	\$ <u>N/B</u>	\$ <u>N/B</u>	

ITEM NO.	DESCRIPTION	QTY.	UOM	PRICE	UNIT	PRICE EXTENSION
362.1	Air Compressor Assembly For 2004 Thomas Built Bus VIN: 1T88N8D2041137565 Engine # 57247333	01	EA.	<u>N/B</u> <u>ext same</u>	\$ <u>1,161-</u> <u>ext same</u>	\$ <u>1810.89</u> <u>ext same</u>
363.1	Air Compressor Assembly For 2005 Thomas Built Bus VIN: 1T88N8E235116113 Engine # 57247333	01	EA.	<u>N/B</u> <u>ext same</u>	\$ <u>1,281-</u> <u>ext same</u>	\$ <u>1810.89</u> <u>ext same</u>
364.1	Fuel Sending Unit For 2004-05 Thomas Built Bus VIN: 1T88N8E2651156217	10	EA.	<u>N/B</u> <u>380-</u>	\$ <u>38-</u> <u>380-</u>	\$ <u>47.14</u> <u>471.40</u>
365.1	Fuel Gauge Assembly For 2004-05 Thomas Built Bus VIN: 1T88N8E2651156217	10	EA.	<u>N/B</u> <u>720-</u>	\$ <u>72-</u> <u>720-</u>	\$ <u>81.88</u> <u>818.80</u>
366.1	Speedometer assembly For 2004-05 Thomas Built Bus VIN: 1T88N8E2651156217	10	EA.	<u>N/B</u> <u>4830-</u>	\$ <u>483-</u> <u>4830-</u>	\$ <u>536.44</u> <u>5304.40</u>
367.1	Fuel Sending unit For 1998 Blue Bird Bus VIN: 1BAAGCSA9TF069398	10	EA.	<u>N/B</u> <u>13040-</u>	\$ <u>130.44</u> <u>1304.40</u>	
368.1	Fuel Gauge assembly For 1998 Blue Bird Bus VIN: 1BAAGCSA9TF069398	10	EA.	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>
369.1	Speedometer Gauge Assembly * For 1998 Blue Bird Bus	10	EA.	<u>N/B</u>	\$ <u>N/B</u>	\$ <u>N/B</u>

370.1 SPRING ACCELERATOR	40	EA.	<u>M/B</u>	\$ <u>3.10</u> <u>124.-</u>	\$ <u>N/B</u>	<u>N/B</u>
371.1 PEDAL ACCELERATOR	06	EA.		\$ <u>20.93</u> <u>125.08</u>	\$ <u>N/B</u>	
372.1 INSULATOR RADIATOR	20	EA.		\$ <u>7.06</u> <u>153.20</u>	\$ <u>N/B</u>	
373.1 KING PIN	06	EA.	<u>N/B</u>	\$ <u>2.98.-</u> <u>1,788.-</u>	\$ <u>390.08</u> <u>2340.48</u>	
For: 1992 Blue Bird School Bus Ref:# 120KK102						
374.1 FUEL PUMP TRANSFER	06	EA.	<u>M/B</u>	\$ <u>85.84</u> <u>875.04</u>	\$ <u>108.41</u> <u>650.46</u>	
Ref: # 4988747						
375.1 WATER PUMP W/GASKET	10	EA.		\$ <u>150.-</u> <u>1,500.-</u>	\$ <u>197.98</u> <u>1979.80</u>	
For: 1992, 1998, 2004, & 2005 School Buses Ref: #4089731						
376.1 LOW AIR SWITCH (60 PSI)	20	EA.		\$ <u>19.-</u> <u>380.-</u>	\$ <u>26.21</u> <u>524.20</u>	
Ref: # 8604						
377.1 EMERGENCY EXIT SWITCH	40	EA.	<u>N/B</u>	\$ <u>14.19</u> <u>567.60</u>	\$ <u>19.22</u> <u>768.80</u>	<u>N/B</u>
For: Thomas Built School Bus Ref:# 7071-101						

# **EXHIBIT “C”**



P.O. Box 20969  
Barrigada, Guam 96921  
United States of America  
671.632.5160

[sales@midpacfareast.com](mailto:sales@midpacfareast.com)

September 28, 2015

Claudia S. Acfalle  
Chief Procurement Office

Re: GSA-093-15

We respectfully take exception to the belief that MPFE total amount on Bid GSA-093-15 is \$295,089.37, when the total of the extended bid prices is \$268,507.87. Therefore our bid bond of \$42,000 is sufficient to meet the requirements and our bid should be considered.

If you do not agree consider this a formal protest of your position.

Should you need further clarification please contact me directly at 487-0936.

Thank you,

Craig Wade  
President/CFO

RECEIVED

Sept 28 PM 1:17

CONT'D ON BACK  
ACF



Allison Transmission



INTERNATIONAL

FEDERAL SIGNAL

KENWORTH



Power Generation

HINO TRUCKS

snorkel

Altec

Bobcat

Dresser Industries

# EXHIBIT “D”

Eddie Baza Calvo

Governor

# GSA

## GENERAL SERVICES AGENCY

(Ahensian Setbision Hinirat)

Department of Administration

Ray Tenorio

Lieutenant Governor

Anthony C. Blaz

Director


148 Route 1 Marine Corps Drive, Piti, Guam 96915

Tel: (671) 475-1707 Fax Nos: (671) 475-1727 / 472-4217

September 29, 2015

### Memorandum

Mr. Craig Wade  
President/CFO  
Mid Pac Far East  
P.O. Box 20960  
Barrigada, Guam 96911



Re: Protest on GSA Bid 093-15


I am in receipt of your memorandum dated September 28, 2015, in which you requested that the submitted bid price be corrected to reflect the error. And, if we fail to change the award based upon your letter, to consider this a protest. Mistakes are defined in 2 GAR. Division 4 Section 3109 (4) (c) which states in pertinent part "Mistakes where intended correct bid is evident" Mistakes where intended correct bid is evident. If the mistake and the intended correct is clearly evident on the face of the bid document. The bid shall be corrected to the intended correct bid and may not be withdrawn. Examples of mistakes that may be clearly evident on the facts of the bid document are typographical errors, errors in extending unit price, transportation errors, and arithmetical errors.

In reviewing your bid submittal, there was no evidence that a mistake occurred.

As stated in the Sealed Bid Solicitation instructions on page 26, item 2(c), in pertinent part: the Unit Price will be presumed to be correct." Your letter of September 28, 2015, reinforced the unit price that you offered.

Therefore, your protest is DENIED.

You have the right to seek any administrative or judicial reviewe authorized by law.

  
CLAUDIA S. ACFALLE  
Chief Procurement Officer

COMMITTED TO EXCELLENCE